

NOTICE OF VIOLATION

Tennessee Valley Authority
Watts Bar Unit 1

Docket No. 50-390
License No. NPF-90

During an NRC inspection conducted from August 11 through September 21, 1996, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," NUREG-1600, the violation is listed below:

Technical Specification 5.7.1.1 requires that written procedures shall be established, implemented, and maintained for activities recommended in Appendix A of Regulatory Guide 1.33, Quality Assurance Program Requirements, Revision 2, February 1978. This includes procedures required for the operational alignment of safety-related equipment.

Watts Bar System Operating Instruction (SOI) 3.02, Auxiliary Feedwater System, Revision 21, Checklist 3, requires the status of isolation valve 1-ISV-3-951 to be open during normal operations.

Contrary to the above, as of September 10, 1996, low pressure steam trap downstream isolation valve 1-ISV-3-951 for low pressure steam trap 1-TRAP-3-936 was closed and was not tracked by any configuration control process for being out of its required position. Isolation of the low pressure trap could potentially degrade the removal of steam condensate from the auxiliary feedwater pump turbine supply line.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Tennessee Valley Authority is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Enclosure 1

9610310172 961017
PDR ADDOCK 05000390
Q PDR

NOV

2

Because your response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if you find it necessary to include such information, you should clearly indicate the specific information that you desire not to be placed in the PDR, and provide the legal basis to support your request for withholding the information from the public.

Dated at Atlanta, Georgia
this 17th day of October 1996