



Acuren Inspection

101 Old Underwood Road
Building J

La Porte, Texas 77571
Office: 281-228-0000
Fax: 281-228-0009

Materials Engineering and Testing
A Rockwood Company

RECEIVED

SEP 28 2007

DNMS

9/27/07

Nuclear Materials Licensing Section
USNRC
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-4005

Attn: Mr. Roberto Torres

Re: License No. 42-27593-01

Subject: Additional information needed to authorize industrial radiography on lay-barges, offshore oil and gas platforms, and in an underwater environment.

Dear Mr. Torres,

In reference to the requested additional information to authorize industrial radiography on lay-barges or offshore platforms, Acuren Inspection does not now perform any industrial radiography on lay barges, offshore oil and gas platforms or underwater environments. In our license application dated May 17, 2005, we didn't actually request authorization to perform offshore industrial radiography but instead checked a wrong box on the Suggested Format for Providing Information. Acuren Inspection has not performed offshore industrial radiography in the last ten years and will not perform offshore industrial radiography in the future. Please remove offshore industrial radiography from our Acuren Radioactive Materials License.

Thank you for your help and if you should have any questions please feel free to call me at (281) 842-3364.

Sincerely,

Gayle J. Staton, Director
Radiation Safety & Environmental Compliance

From: Origin ID: BBCA (281)228-0000
ACUREN INSPECTION

101 OLD UNDERWOOD RD
BLDG J
LA PORTE, TX 77571



CL990007/2123

Ship Date: 27SEP07
ActWgt: 1 LB
System#: 4813775/INET7091
Account#: S *****

Delivery Address Bar Code



Ref #
Invoice #
PO #
Dept #

SHIP TO: (860)817-8189

BILL SENDER

Roberto Torres
USNRC
611 RYAN PLAZA DR STE 400


ARLINGTON, TX 760114005

FRI - 28SEP

A1


TRK# 7924 2740 6051
0201

PRIORITY OVERNIGHT



AD-FWHA

DFW
TX-US
76011



Shipping Label: Your shipment is complete

1. Use the 'Print' feature from your browser to send this page to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our Service Guide. Written claims must be filed within strict time limits, see current FedEx Service Guide.