NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201					
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
LICENSEE/LOCATION INSPECTED: Cardiac Imaging Center, PLLC 331 Laidley Street, Suite 402 Charleston, West Virginia REPORT Nos 2007-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(3)	5. DATE(S) OF INSPECTION	ON
030-36436		47-30849-01	September 13 8		2007
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Dennis Lawyer		Denner	ý	9/28/2007
NRC FORM 591M PAR	1 (Rev. by RI 07/06)		F:\lnsner	tion\R47-30849-01,2007-00	591M-Part1 wnd

SUNSI Review Completed By: /RA/ Dennis Lawyer X Public X Non-Sensitive