

John T. ...
Tel: 03/09/200
Collected by Jay ...

Davis Besse

we have no condition Report.

Davis Besse Condition Report.

Crack growth rate much higher

① submitted a claim recovery of cost
as part of Claimed. Exponent provided an
Analysis/report.

NEIL reviewed the report, identified a safety concern.

MRP 75% for industry in MRP

heat of → 95% crack growth rate in Davis Besse.
material from Midland but Davis Besse does not have
the Midland heat of material.

Same heat as in Oconee in Davis Besse

M3139 heat 5

A-1