

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

|                                                                                                                      |                                      |                                                                                                                      |  |
|----------------------------------------------------------------------------------------------------------------------|--------------------------------------|----------------------------------------------------------------------------------------------------------------------|--|
| 1. LICENSEE/LOCATION INSPECTED:<br>Testmaster Inspection Co<br>P.O. Box 31<br>Perrysburg, OH 43552<br>REPORT 2007001 |                                      | 2. NRC/REGIONAL OFFICE<br>US Nuclear Regulatory Comm<br>Reg III<br>2443 Warrenton Rd<br>Suite 210<br>Lisle, IL 60532 |  |
| 3. DOCKET NUMBER(S)<br>03035090                                                                                      | 4. LICENSEE NUMBER(S)<br>34-24872-02 | 5. DATE(S) OF INSPECTION<br>10/26/07                                                                                 |  |

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title                     | Printed Name | Signature | Date     |
|---------------------------|--------------|-----------|----------|
| LICENSEE'S REPRESENTATIVE |              |           |          |
| NRC INSPECTOR             | G. Parker    |           | 10/26/07 |

**Docket File Information**  
**SAFETY INSPECTION REPORT**  
**AND COMPLIANCE INSPECTION**



|                                                                          |                                            |                                              |  |
|--------------------------------------------------------------------------|--------------------------------------------|----------------------------------------------|--|
| 1. LICENSEE<br><b>Testmaster Inspection</b><br>REPORT NUMBER(S) 2007-001 |                                            | 2. NRC/REGIONAL OFFICE<br><b>Region III</b>  |  |
| 3. DOCKET NUMBER(S)<br>030-35090                                         | 4. LICENSE NUMBER(S)<br>34-24872-02        | 5. DATE(S) OF INSPECTION<br>October 26, 2007 |  |
| 6. INSPECTION PROCEDURES USED<br>87126                                   | 7. INSPECTION FOCUS AREAS<br>03.01 - 03.07 |                                              |  |

**SUPPLEMENTAL INSPECTION INFORMATION**

|                             |                  |                                     |                                     |
|-----------------------------|------------------|-------------------------------------|-------------------------------------|
| 1. PROGRAM CODE(S)<br>03320 | 2. PRIORITY<br>1 | 3. LICENSEE CONTACT<br>Wendell Carr | 4. TELEPHONE NUMBER<br>419/666-7526 |
|-----------------------------|------------------|-------------------------------------|-------------------------------------|

Main Office Inspection      Next Inspection Date: 10/08

Field Office \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is an industrial radiographer located in Perrysburg, Ohio with authorization to use material at temporary job sites where the NRC maintains jurisdiction. This licensee has four full time radiographers and is in possession of twelve 660 exposure devices containing sources up to 100 curies each.

**Performance Observations**

At the time of the inspection, licensee was performing radiography only in Ohio. The inspection of facilities was limited in scope since licensee is located in an Agreement State. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were generally low and ranged to 1500 mRem/yr.

No violations of requirements were noted.