

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

50-390

December 6, 1974

Mr. Donald F. Knuth, Director  
Directorate of Regulatory Operations  
U.S. Atomic Energy Commission  
Washington, DC 20545

Dear Mr. Knuth:

WATTS BAR NUCLEAR PLANT - CONCRETE FORM FAILURE ON  
ROOF SLAB OF CONTROL BUILDING

Initial report of the subject incident was made to  
L. F. Foster, AEC-DRO Region II inspector, on November 6,  
1974. In compliance with paragraph 50.55(e) of 10 CFR  
Part 50, this is submitted as an interim report. Investi-  
gation and analysis associated with the subject incident  
have not been completed. We expect that we should be able  
to provide the final report by January 15, 1975.

Very truly yours,



J. E. Gilleland  
Assistant to the Manager of Power

CC: Mr. Norman C. Moseley, Director  
Directorate of Regulatory Operations  
U.S. Atomic Energy Commission  
Region II - Suite 818  
230 Peachtree Street, NW.  
Atlanta, Georgia 30303

4 2117