

U.S. Geological Survey
MS 966, Box 25046
DFC
Denver, CO 80225
303-273-8556
fax 303-273-8600
afrankel@usgs.gov
June 30, 2004

Dr. Andrew Murphy
U.S. Nuclear Regulatory Commission

Dr. Murphy,

Enclosed is a CD containing the corrected seismic hazard results for the 29 sites. The corrections only involve the PGA, 5 Hz, and 1 Hz results. These corrections are explained in the README file. The mean and median hazard curves are only slightly changed by the correction. The 5th and 15th fractile curves are significantly changed.

Sincerely,

Arthur Frankel

A-7