



Q-5

5 December 2007

Betsy Ullrich  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

VIA fax: 610-337-5269

RE: 37-00030-08 & ~~37-00030-106~~

03005982 WA  
Dear Betsy;

We are requesting an expedited, one-time amendment to the above referenced license which will allow an aircraft customer to return to our facility to conform (inspect) parts that they have already purchased and received from us. This conformance inspection is required of our customer, by the FAA.

It simply requires that the customer witness the final inspection at the manufacturing location and apply quality stamps to the part and the necessary paperwork at that time.

The customer is Midcoast aviation. They would like to return no more than 4 pieces of AC/31 Series parts under RMA#5464-SPL. Upon their witnessing of the conformance inspection, we would immediately re-ship the parts back to Midcoast.

Thank you for your consideration to this unanticipated situation.

Regards,

Martha J. Rider  
Radiation Safety Officer

SAFETY LIGHT CORPORATION • 4150-A Old Berwick Road • Bloomsburg, PA 17815  
570.784.4344 • fax 570.784.1402 • www.safetyslight.com

141383

NMSS/RGN1 MATERIALS-002

No. 8505 P. 1

Dec. 5, 2007 2:02PM Safety Light Corp