

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

July 1, 1980

~~Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303~~

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - SAFETY-RELATED CABLE INSIDE
CONTAINMENT NOT QUALIFIED - NCR WBN QEB 8001 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector M. Thomas on March 31, 1980, in accordance with 10 CFR 50.55(e). Our first interim report was submitted on April 24, 1980. TVA is continuing to investigate the radiation qualification of safety-related cables enclosed in conduit inside containment. After the radiation qualification of these cables has been evaluated, a report detailing the results of the evaluation and TVA's corrective actions will be submitted to NRC-OIE. We expect to submit our next report by September 19, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/0

8007090 222