

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

August 5, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 - SIS TRAIN B FLOW DEFICIENT- NCR WBN NEB
8004 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector J. D. Wilcox on May 1, 1980, in accordance with 10 CFR 50.55(e). Our first interim report was submitted on May 30, 1980.

TVA is continuing the evaluation to define the cause of the flow reduction. We will provide additional information by November 7, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

3019
S 1/0

8008120425

5