

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

830 Power Building

Central File
50-390
391

November 9, 1978

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - ICE CONDENSER STRUCTURE BOLTS
OVERTORQUED - NCR 1226R - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
E. O. Porter on July 27, 1978, and an interim report was submitted on
August 25, 1978. Enclosed is our final report.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,



J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

23 : 11 P NOV 13 1978

RECEIVED
ATLANTA, GEORGIA
NOV 13 1978

7812050266

MA 1
S
60