

1 EHQ5

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

MAY 24 1979

79 MAY 29 A 8 : 50

USNRC REGION II
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - POTENTIAL INFERIOR STRUCTURAL
STEEL CONTAINMENT VESSEL MOVEMENT ENVELOPE - NCR 1319R - SECOND
INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
B. Cochran on January 2, 1979. Our first interim report was submitted
on February 1, 1979.

TVA's analysis of the as-built condition has not been completed. We
expect to submit our next report by September 17, 1979.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland

J. E. Gilleland
Assistant Manager of Power

cc: Mr. John G. Davis, Acting Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCUMENT COPY

B019
S/0
-1

790160

7906140 452