

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

JUN 20 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH AND WATTS BAR NUCLEAR PLANTS - MOV CONTROL CIRCUIT FAILURE -
NCR 700 AND NCR 714 - REVISED FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector J. K. Rausch on February 16, 1978, in accordance with 10 CFR 50.55(e). An interim report was submitted on March 17, 1978 and a final report was submitted June 16, 1978. A revised final report was submitted on July 5, 1978. Enclosed is a further revised final report as requested by T. E. Conlon.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

B019
S 1/1

7906270 224