

79-024-03L  
79-023-03L

15 MAR 1979

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

July 3, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

REGULATORY DOCKET FILE COPY

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - ERCW VALVE POSITIONING -  
NCR MEB 79-23 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector B. J. Cochran on June 7, 1979, in accordance with 10 CFR 50.55(e). Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

*L. M. Mills*

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

3019  
S 1/1

790224

7908020488