

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

August 22, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 NCR SWP 79-S-9 AND WATTS BAR NUCLEAR
PLANT UNITS 1 AND 2 NCR SWP 79-W-9 - INSUFFICIENT FLEXIBILITY OF LOW HEAD
INJECTION TEST LINES - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. J. Gouge on July 27, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our final report.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stallo, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

Boia
S/11