

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 3, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - INSUFFICIENT ANALYSIS OF 3-INCH  
FIRE PROTECTION LINES - NCR WBN CEB 8005 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
M. Thomas on June 6, 1980, in accordance with 10 CFR 50.55(e).

In our first interim report dated July 23, 1980, TVA stated that 3-inch  
fire protection lines would be rigorously analyzed. This analysis has  
been delayed. We expect to provide additional information by November 25,  
1980.

If you have any questions, please get in touch with D. L. Lambert at  
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

B019  
S 1/0

8009100443 S