

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

5N 157B Lookout Place

March 18, 1986

Director of Nuclear Reactor Regulation
Attention: Mr. B. J. Youngblood, Project Director
PWR Project Directorate No. 4
Division of Pressurized Water Reactor (PWR)
Licensing A
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Youngblood:

In the Matter of the Application of) Docket Nos. 50-390
Tennessee Valley Authority) 50-391

Please refer to J. A. Domer's letter to E. Adensam dated January 24, 1986 concerning compliance with the guidelines of NUREG-0612. The letter provided information that lift beams LD10 and LD31 would be in compliance about March 1, 1986. This date has not been met. Equipment received via contract to complete the modification lacked proper certification and replacement equipment has not been received. As previously stated in Mr. Domer's letter to Ms. Adensam dated January 16, 1985, the lifting devices will not be required for use until the beginning of the first refueling outage. They will be in compliance by that time.

If there are any questions, please get in touch with K. P. Parr at FTS 858-2681.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Domer
R. L. Gridley
Manager of Licensing

cc: U.S. Nuclear Regulatory Commission
Region II
Attention: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

8603250171 860318
PDR ADOCK 05000390
A PDR

A033
1/0