e .				
WATTS	BAR	NUCLEAR	PLANI	

TECHNICAL INSTRUCTION

<u>TI-50B</u>

ASME SECTION XI

PRESERVICE INSPECTION PROGRAM

UNIT 2

CURRENT REVISION LEVEL 9				
Responsible Section ISI Programs				
Prepared By Jeffery C. Goulart				
Revised ByJeffery C. Goulart				
Submitted By Man Supervisor				
• Supervisor				
PORC Review Date 3/35/87				
Approved By <u>ficillos Offorman</u> /Plant Manager				
Date Approved <u>3/35757</u>				

Last page of this instruction: 332

8707310020 870727 PDR ADUCK 05000390

Doc Control Unit, LP 4S 160D-C NRC NSRS, E3A 12C-K Plant Master File Plant Manager Supt (O&E) Supt (Maint) ASE Duty Station Building Services Supv Chem Engg Unit Supv Chief, Nuclear Safety Staff Chief, Nuclear Training Branch Chief, Quality Audits Branch Compliance Unit Component Engg & Svs Group DNE /(A Dwg & Vendor Manual Supv Elect Eng Br - K Engg Section Supv Health Physics Supv Industrial Safety Supv Instr Maint Supv Materials Unit Supv TU. Mech Maint Supv 10 Mech Shop Office Modifications Manager Operating Instruction Coordinator Operations Supv IC Operations Training Sect Supv Operator Training Classroom aic Plant QA Supv Power Stores Unit Supv Preop Test Supv Reactor Engg Unit Supv Shift Engr's Office Staff Reference Copy Support Svs Supv Tech Support Center Unit 1 Control Rm Unit 2 Control Rm /C_ John Raulston, NEB, W10A63 C-K 10 Site Procedure Watts Bar Tech Svs Design Svs Manager Inservice Inspection Group-C ISI Program Section-C _ NDE Engineering Section-C NDE Engineering Section-WBNP NDE Inspection Section-C NDE Inspection Section-WBNP DCU-B-WBNP-CC-Kenny Cole 11 FC ANI-WB DCU 8 - hr sta DCU 24 - hr sta 10

WBNP TI-50B

 $\int c$

ß

Page 1 of 1

HISTORY OF REVISION/REVIEW

REV. NO.	DATE	REVISED PAGES	-REASON FOR CURRENT REVISION (INCLUDE ALL TEMPORARY CHANGE NUMBERS)
3	11/03/82	51, add 79A-79P	Add weld location drawings to Appendix A
4	03/22/83	Page 1	Change WB7.3.8 to AI-9.7
5	10/17/83	Pages 32, 33, 50	Incorporated the changes in N-OQAM, Part II, Section 5.1
6	10/02/84	A11	General revision to update program, added drawings, tables, Request for Relief and renumbered all pages, incorporated temporary change TC-84-192
7	05/29/85	Cover sheet, Table of Contents, punch list. 2, 3, 4, 7, 16, 23, 24, 27, 28,	Minor changes, updated pipe welds and dissimilar metal welds to 1977 edition, summer 1978 addenda of ASME SECTION XI, added weld location drawings.
		40, 43, 44, 48, 48a, 49, 51, 66, 88, 89, 91, 92, 110-114, 116-146, 201, 203-212, 284, 285-290, 292, 294, 296, 307	ι
8	10/03/86	Cover sheet, Table of Contents, 1-6, 8, 11, 12, 16, 21, 26, 31-33, 35, 36, 38, 39, 40, 40a, 284, 288, 289, 291 Added page 39a, 6a	Two year review, minor corrections and clarifications, and incorporated NQAM, Part II, Section 5.1 revision dated 6-20-86 changes. Also, added check-offs for USQD and condition potentially significant and/or potentially reportable to the notification of of indication form.
9	3/25/37	Punchlist, 2, 4, 7, 38, 39 39a, 40, 291,	NOI section and NOI form revised to incorporate the requirements of NQAM, PART I, Section 2.16 Revision 2, Corrective Action. Added the use of Code Case N-416. Made minor correction and clarifications.

WBNP TI-50B Page 1 of 1 Revision 9

Punchlist

) The requirement contained in paragraph 7 of Section 16.0 "Notification of Indication" to issue an Unreviewed Safety Question Determination (USQD) for each NOI which is dispositioned "use-as-is" cannot be physically implemented until 30 days prior to fuel load due to the punchlist to AI-2.18. NOI's which will be dispositioned "use-as-is" will be held open until Watts Bar AI-2.18 is implemented. Once AI-2.18 is implemented, USQD's will be prepared in accordance with AI-2.18 and the NOI's will be closed.

22

(1)

WBNP TI-50B Page 2 of 40 Revision.9

This program was prepared to meet the requirements of the 1974 Edition, Summer 1975 Addenda of Section XI of the ASME Boiler and Pressure Vessel Code.

Procedures for eddy current examination of heat exchanger tubing, which the Summer 1975 Addenda of ASME Section XI has no provisions for, meets the requirements of the 1974 Eddition, Summer 1976 Addenda of ASME Section XI. Steam generator tubing examination requirements are in accordance with a modification of Regulatory Guide 1.83, Revision 1.

The following categories shall be in accordance with the 1977 Edition, Summer 1978 Addenda of Section XI:

- (1) Class 2 pressure-retaining bolting.
- (2) Class 2 valve body weld examinations
- (3) Component support integrally-welded attachment examinations for piping, pumps, valves and pressure vessels.
- (4) Component support examinations for piping, pumps and valves.
- (5) Interior clad surfaces of reactor vessels and other vessels examination are not required.
- (6) Reactor vessel interior and core support structure examinations.
- (7) Parts examined, examination requirements figure number, examination techniques and acceptance standards in accordance with Table IWB-2500-1 for examination categories B-F (except item No. B5.10 - reactor vessel nozzle-to-safe end welds) and B-J, and Table IWC-2500-1 for examination category C-F. Ultrasonic examination techniques in accordance with IWA-2232 (b) and (c) and ultrasonic evaluation standards IWA-3000. (See Request for Relief ISI-1 and ISI-2).

The repair and replacement program is in accordance with plant instruction AI-9.15 and Program Procedure 1402.02.

The use of code cases N-234, N-235, N-401 and N-416 have been approved for TVA use by NRC.

4.0 METHOD OF IMPLEMENTATION AND RESPONSIBILITIES

Preliminary weld maps and other pertinent component drawings and tables are included in Appendix A of this program to define areas subject to examination (in addition to sections 5.0, 6.0, 7.0, and 8.0). The preliminary piping weld maps should be established by ISI Programs Section of the Inservice Inspection Group, Mechanical Services Branch, Operations Engineering Services, Division of Nuclear Engineering from Division of Nuclear Construction's latest revision weld maps.

WBNP TI-50B Page 4 of 40 Revision.9

Additionally, the Inservice Inspection Group representative will be responsible for notifying the Plant Manager of all unacceptable indications as soon as practical. Whenever an unacceptable indication is discovered, this procedure (Section 16.0) and the Notification of Indication (NOI) form in Appendix C shall be utilized. In those cases where an outside contractor is furnishing preservice examination services, the contractor will normally initiate the form in Appendix C under the supervision of the Inservice Inspection Group representative. See section 16.0 of this program.

Computer monitor programs are used to identify any welds or supports that have been reworked by Division Nuclear Construction after the preservice examination has been done. The Plant shall include provisions for notifying Inservice Inspection Group in any work instruction written to modify or rework welds or supports after the preservice examination has been done.

The Inservice Inspection Group shall maintain the status of completed examinations for each weld or component support required to be examined. Individual component status is kept by transferring all the information from the scan plan to a master plan, as examinations are preformed they are recorded in the master plan for status.

As sections are completed, the NDE Inspection Section representative shall sign for completion the appropriate sections of Data Sheet 1 in Appendix B of this program. When all examinations of this program have been completed, Data Sheet 1 shall be signed for completion by the NDE Inspection Section representative and reviewed by the NDE Engineering Section Supervisor, ISI Programs Section Supervisor, and approved by Inservice Inspection Group Supervisor. In the event system or component alterations or repairs are made which require component reexamination, or components are reexamined for other reasons, following sign-off of Data Sheet 1, the appropriate sections of Data Sheet 2 in Appendix B shall be completed and signed by the NDE Inspection Supervisor, ISI Section Supervisor, and approved by the Inservice Inspection Group Supervisor.

All preservice examinations shall be completed prior to initial plant startup (Operational Mode 2). Prior to initial plant startup, Data Sheet 2, in addition to Data Sheet 1, in Appendix B shall be signed by the NDE Inspection Section representative and reviewed by the NDE Engineering Section Supervisor, and the ISI Programs Supervisor, and approved by the Supervisor of the Inservice Inspection Group. After the data sheets 1 and 2 have been approved, the data package cover sheet shall be signed by the Mechanical Services Branch Chief and the Plant Manager. These data sheets shall be filed at the plant site with PSI examination data and final reports discussed in Section 15.0 of this program.

PSI program preparation is the responsibility of ISI Programs Section. Any revisions initiated by other groups shall be submitted to the ISI Programs Section for approval prior to incorporating the revisions into this program.

WBNP TI-50B Page 7 of 40 Revision 9

When examinations have been completed on the various components, the data sheet(s) in Appendix B shall be completed.

Table A in Appendix A supplies additional information such as reference drawing numbers and Section XI, Table IWB-2600, examination categories.

6.1 <u>Reactor Vessel</u>

6.1.1 Reactor Vessel Seam Weld

6.1.1.1 Circumferential Shell Weld - Beltline Region

There is one circumferential weld in the vessel cylinderical shell located behind the neutron shield pads. This weld will be ultrasonically examined using remote inspection devices from the vessel I.D. with the core internals removed. The vessel shell sections are machined forgings fabricated of SA-508, Class 2, manganese-molyedenum steel and are clad with weld deposited austenitic stainless steel.

There are no base metal repair welds in the beltline region where repair dept exceeds 10% nominal of vessel wall.

6.1.1.2 Circumferential Shell Welds

There are three circumferential welds in the vessel cylinderical shell located outside of the beltline region. These welds will be ultrasonically examined using remote inspection devices from the vessel I.D. with the core internals removed.

The vessel shell section material is identified in section 6.1.1.1.

6.1.1.3 Lower Head Welds

There are six meridional welds and one circumferential weld in the lower head. The welds will be ultrasonically examined using remote inspection devices from the vessel I.D. with the core internals removed.

Base metal below the lower head circumferential weld is inaccessible for examination from the vessel I.D. due to instrumentation penetrations (weld No. WO1-02). A manual ultrasonic examination of this area will be conducted from the vessel O.D. (see Request for Relief ISI-4).

WBNP TI-50B Page 38 of 40 Revision 9

16.0 NOTIFICATION OF INDICATION

Plant management shall be formally notified of the presence of unacceptable indications detected during the performance of nondestructive examinations (excluding VT-2, visual examinations performed during system pressure test). Unacceptable indications are defined by the applicable NDE procedure. Formal notification shall consist of completing and submitting to the Plant Manager the "Notification of Indication" (NOI) form in Appendix C of this program. The NOI form shall only be used to report unacceptable indications of components within the scope of Section XI and which have been scheduled for examination. Any other discrepancies should be reported in accordance with the appropriate plant procedure (e.g., MR, WR, etc.).

NOIs initiated prior to the requirement of a Condition Adverse to Quality Report (CAQR) and the implementation of Revision 9 of this instruction shall be handled as NOIs for which no Condition Adverse to Quality has been identified.

Part I of the NOI shall be completed and signed by the NDE Level II or III examiner detecting the indication. The examiner detecting the indication can initiate a CAQR at this time or defer the decision to the individual responsible for the disposition in Part II of the NOI form. The NOI form and the CAQR are to be processed together. The ISI Group (NDE Inspection Section) representative shall assign a sequential number and review and sign the NOI form. If the indication is detected by an outside contractor, the contractor's field supervisor shall review and sign the NOI form. A NOI log shall be maintained on a plant/unit/cycle basis by the NDE Inspection Section for each NOI issued. This log shall contain as a minimum: NOI No., component I.D., date issued, examination report No., unsatisfactory condition, MR/WR No., and work instruction and/or DCR numbers as applicable. The original shall be sent to the plant manager and a copy to the ISI Group (ISI Programs Section).

In the case of NOIs for which no Condition Adverse to Quality (CAQ) has been identified, the Nuclear Site Director's organization shall be responsible for determining which organization (construction, modification, plant maintenance, etc.) shall be responsible for preparing a disposition in Part II of the NOI form and performing the associated corrective action. If the organization assigned responsibility for disposition is unable to determine a satisfactory disposition then the NOI form should be sent to the Mechanical Services Branch for disposition.

The organization assigned responsibility for the disposition shall evaluate the NOI for the need of a CAQR in accordance with the NQAM Part I, Section 2.16 and plant instruction AI-2.8.5, the CAQR shall be processed in accordance with AI-2.8.5. If a CAQR is needed, enter the identifying number of the CAQR in the space shown on the NOI form. The NOI form and the CAQR are to be processed together. WBNP TI-50B Page 39 of 40 Revision_9

The individual responsible for preparation of the disposition shall sign and date Part II of the NOI form and ensure that the disposition agrees with the corrective action proposed in the CAQR if one was initiated. The cognizant supervisor of the appropriate organization shall review and approve the disposition and sign and date Part II of the form. Copies of the NOI form shall be distributed to the plant manager and the ISI GROUP (ISI Programs Section). The original shall be returned to the ISI Group (NDE Inspection Section) Representative. One copy shall be filed with the examination report.

Dispositions to correct the condition under the plant maintenance program shall be processed in accordance with NQAM, Part II, Section 2.1 and Plant Instruction AI-9.2. Dispositions other than restoring to original requirements shall be processed as modifications in accordance with NQAM, Part II, Section 3.0 and Plant Instruction AI-8.5 before licensing and AI-8.8 after licensing. Repair and replacement, activities, including coordination with the Authorized Inspection Agency (AIA), shall be performed in accordance with the requirements of NQAM, Part II, Section 2.3 and Plant Instruction AI-9.15. Dispositions to accept the condition as-is shall include in Part II of the form NOI the basis for the disposition. In addition for dispositions to accept the condition as-is, a USQD shall be prepared by the appropriate organization in accordance with established procedures and a copy submitted along with the NOI form.

If Division Nuclear Construction is responsible for corrective action, it shall be performed in accordance with the disposition on the NOI form and to the satisfaction of the ISI Group (NDE Inspection section) representative. The organization responsible for corrective action shall include preservice examination requirements in the repair or replacement work instruction described in NQAM Part II, Section 2.3 and Plant Instruction AI-9.15.

Upon completion of corrective action the ISI GROUP (NDE Inspection Section) Representative shall verify completion of corrective action, enter the work instruction and/or Design Change Request (DCR) numbers on the NOI form, enter the examination report number if reexamination was performed, and sign and date the NOI form, Part III. The signed NOI form shall remain with the examination report for use as a quality assurance record. If reexamination was performed, a copy of the signed NOI form shall also remain with the reexamination report. Copies of the NOI form shall also be distributed to the plant manager and the ISI Group (ISI Programs Section). WBNP TI-50B Page 39a of 40 Revision 9

.17.0 CALIBRATION BLOCKS

Calibration blocks will be used for ultrasonic examinations (a calibration tube will be used for eddy current examination of steam generator tubing). The blocks will be fabricated to the general requirements of ASME Section V and ASME Section XI. The blocks shall be fabricated of the material to be examined or equivalent P numbers. Mill test reports shall be obtained and retained by the NDE Inspection Section for all calibration blocks. The blocks shall employ drilled holes and/or notches for calibration reflectors (see Request For Relief ISI-1).

The NDE Inspection Section shall ensure that as built calibration block drawings are prepared. The calibration block drawings shall be maintained in accordance with NQAM, Part II, Section 6.3.

18.0 REQUESTS FOR RELIEF

Where TVA has determined that certain code requirements or examinations are impractical, Mechanical Services Branch will submit these request for relief to the NRC for approval via ONP Nuclear Safety and Licensing with information to support the determinations and any proposed alternate examinations. The impractical code requirements or examinations shall be identified in this program, and references to particular requests for relief shall be included.

When impractical examination requirements are identified in the field, the NDE Inspection Section or NDE Engineering Section shall notify the ISI Programs Section such that the information may be included in this program and requests for relief may be prepared if necessary. The NDE Inspection Section or NDE Engineering Section shall submit sketches to the ISI Programs Section to identify areas which cannot be examined in accordance with code requirements. WBNP TI-50B Page 40 of 40 Revision 9

19.0 AUGMENTED INSPECTIONS

19.1 Steam Generator Tubes

The augumented examination requirements of the steam generator tubing are included in Technical Specification 4.4.5.0 and Section 6.3.8 of this program.

20.0 REFERENCES

- 20.1 Source Documents
 - 20.1.1 ASME Boiler and Pressure Vessel Code Section XI through Summer 1975 addenda, Summer 1976 addenda, Summer 1978 addenda.
 - 20.1.2 ASME Boiler and Pressure Vessel Code Section V through Summer 1975 addenda.
 - 20.1.3 Watts Bar Nuclear Plant Final Safety Analysis Report.
 - 20.1.4 Nuclear Quality Assurance Manual, Part I, Section 2.16
 - 20.1.5 Nuclear Quality Assurance Manual Part II, Section 2.1, 2.3, 4.1, 5.1, and 6.3.
 - 20.1.6 Nuclear Quality Assurance Manual Part III, Section 1.1.
 - 20.1.7 Code of Federal Regulation, Title 10, Part 50.55a.

20.1.8 U.S. Nuclear Regulatory Commission Regulatory Guide 1.14, 1.26, and 1.83.

20.1.9 Watts Bar Nuclear Plant Technical Specifications.

- 20.2 Other Documents:
 - 20.2.1 Instruction Manual 173-inch I.D. Reactor Pressure Vessel - Rotterdam Dockyard Company, Contract No. 71C62-54114-1, N3M-2-3.
 - 20.2.2 Westinghouse Technical Manual Pressurizer, TM 1440-C225, Contract No. 71C60-54114-1, N3M-2-6.
 - 20.2.3 Westinghouse Technical Manual Vertical Steam Generators, TM 1440-C254, Contract No. 71C62-54114-1, N3M-2-4.
 - 20.2.4 Westinghouse Instruction Manual Auxiliary Heat Exchangers, Contract No. 71C62-54114-1, N3M-2-30.
 - 20.2.5 Westinghouse Instruction Book Reactor Coolant Pump, Contract No. 71C62-54114-1, N3M-2-5.

• • •	APPEN	DIX C	WBNP
	NOTIFICATION	OF INDICATION	TI-50B Appendix C
- - 		2 AM	Page 1 of 1
	PARI I	- FINDINGS	Revision 9
Examination Report No.		•	
	<u></u>	•	•
Description of Indicati			
		·······	······································
			·
Condition Adverse to Qu Part II below, Yes with NQAM Part I, Sect	, CAQR No. entere	d above and CAQR pro	cessed in accordan
Signature of Examiner/(Certif. Level		• • • • • • • • • • • • • • • • • • •
Signature of Field Supe	ervisor (Contract	.or)	Date
ISI Group Representativ			Date
isi Group Representativ	ve		Date
Accienced to:			
Assigned to:		Organizatio	e Director's on Representative
	PART II -	Nuclear Sit	
 Condition Adverse to Qu Above), No, Yes	uality Report (CA s, and processed	Nuclear Sit Organizatic DISPOSITION QR) required?	n Representative
Condition Adverse to Qu Above), No, Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached.	uality Report (CA s, and processed Instruction AI-7 tion Determinatio	Nuclear Sit Organizatic DISPOSITION QR) required? in accordance with N .3. n (USQD) required	on Representative See Part I QAM Part I, No, Yes
Condition Adverse to Qu Above), No, Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By	uality Report (CA s, and processed Instruction AI-7 tion Determinatio	Nuclear Sit Organizatic DISPOSITION QR) required? in accordance with N .3. n (USQD) required	Date
Condition Adverse to Qu Above), No, Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By	uality Report (CA s, and processed Instruction AI-7 tion Determinatio	Nuclear Sit Organizatic DISPOSITION QR) required? in accordance with N .3. n (USQD) required	on Representative See Part I IQAM Part I, No, Yes Date
Condition Adverse to Qu Above), No, Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By	uality Report (CA s, and processed Instruction AI-7 tion Determinatio	Nuclear Sit Organizatio DISPOSITION QR) required?(in accordance with N .3. n (USQD) required	Date
Condition Adverse to Qu Above), No, Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By	uality Report (CA s, and processed Instruction AI-7 tion Determinatio	Nuclear Sit Organizatic DISPOSITION QR) required? in accordance with N .3. n (USQD) required	on Representative See Part I IQAM Part I, No,Yes Date
Condition Adverse to Qu Above),No,Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By Disposition Approved By Verification of Complet Representative	uality Report (CA s, and processed Instruction AI-7 tion Determinatio y PART III - ted Corrective Ac	Nuclear Sit Organizatio DISPOSITION QR) required?(in accordance with N .3. n (USQD) required VERIFICATION tion and/or Examinat	on Representative See Part I IQAM Part I, Date Date Date
Condition Adverse to Qu Above), No, Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By Disposition Approved By Verification of Complet Representative	PART III -	Nuclear Sit Organizatio DISPOSITION QR) required?(in accordance with N .3. n (USQD) required VERIFICATION tion and/or Examinat	on Representative
Condition Adverse to Qu Above),No,Yes Section 2.16 and Plant Unreviewed Safety Quest copy attached. Disposition Prepared By Disposition Approved By Verification of Complet Representative	PART III -	Nuclear Sit Organizatio DISPOSITION QR) required?(in accordance with N .3. n (USQD) required VERIFICATION tion and/or Examinat	on Representative

ł

1

C

(

TI-50B - APPENDIX C