



Tennessee Valley Authority, 1101 Market Street, Chattanooga, Tennessee 37402

FEB 21 1991

WBRD-50-390/90-04

10 CFR 50.55(e)

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:

In the Matter of the Application of) Docket Nos. 50-390
Tennessee Valley Authority)

WATTS BAR NUCLEAR PLANT (WBN) UNITS 1 - CABLES DAMAGE AT SPLICES -
WBRD-50-390/90-04 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC Region II on November 1, 1990, in accordance with 10 CFR 50.55(e) as Condition Adverse to Quality Report WBP 900450. TVA submitted an interim report for this issue on November 30, 1990.

The Region II staff was notified on February 1, 1991, that the final report would be delayed. Field inspections required to determine the extent of the condition will be completed once work resumes in the field. TVA expects to finalize corrective actions and submit a final report approximately six weeks after completion of the inspections following resumption of electrical field construction activities.

If there are any questions, please telephone P. L. Pace at (615) 365-1824.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

E. G. Wallace, Manager
Nuclear Licensing and
Regulatory Affairs

cc: See page 2

286042
9102260260 910221
PDR ADOCK 05000390
S PDR

IE27

U.S. Nuclear Regulatory Commission

cc: Ms. S. C. Black, Deputy Director
Project Directorate II-4
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852 -

NRC Resident Inspector
Watts Bar Nuclear Plant
P.O. Box 700
Spring City, Tennessee 37381

Mr. P. S. Tam, Senior Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

Mr. B. A. Wilson, Project Chief
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323