

MIDWEST CARDIOLOGY ASSOCIATES  
5701 W. 119<sup>TH</sup> STREET, SUITE 430  
OVERLAND PARK, KS 66209

## FACSIMILE TRANSMITTAL SHEET

TO:

Loren Hueter

FROM:

DORIANN C. SHULER

COMPANY:

NUCLEAR REGULATORY

DATE:

01-09-08

FAX NUMBER:

630-515-1078

TOTAL NO. OF PAGES INCLUDING COVER:

PHONE NUMBER:

630-829-9829

SENDER'S REFERENCE NUMBER:

913-253-3046 Phone

RE:

SENDER FAX REFERENCE NUMBER:

913-663-2980 - FAX

☒ URGENT    ☒ FOR REVIEW    ☐ PLEASE COMMENT    ☐ PLEASE REPLY    ☐ PLEASE RECYCLE

NOTES/COMMENTS:

Thanks, Doriann

dshuler@midwestcardiology.com

## NOTICE: - PROHIBITION ON REDISCLOSURE

This transmission (and any information attached to it) may be confidential and is intended solely for the use of the individual or entity to which it is addressed. If you are not the intended recipient or the person responsible for delivering the transmission to the intended recipient, be advised that you have received this transmission in error and that any use, dissemination, forwarding printing or copying of this information is strictly prohibited. If you have received this transmission in error, please immediately

**MIDWEST CARDIOLOGY ASSOCIATES, P.A.**

5701 WEST 119th STREET  
SUITE 430  
OVERLAND PARK, KS 66209  
(913) 253-3000 FAX: (913) 253-3030

10550 QUITVIRA ROAD  
SUITE 510  
OVERLAND PARK, KS 66215  
(913) 894-9015 FAX: (913) 541-9516

19550 E. 39th STREET  
SUITE 210  
INDEPENDENCE, MO 64057  
(816) 478-9071 FAX: (816) 478-9144

DANIEL L. SCHARF, MD, FACP, FACC  
BERNARD LEVI, MD, FAC, FACC  
STEPHEN A. BLOOM, MD, FACP, FAHA, FASNC, FACC  
LLOYD D. STAHL, MD, FACP, FACC  
ALAN M. SCHNEIDER, MD, FACC

UJJAVAL M. PATEL, MD, FACC  
KARL D. PFUETZE, MD  
PAUL NAGER, DO, FACC, FACP  
PETER H. PARK, M.D., FACC  
ELIZABETH V. DANG, M.D.

January 9, 2008

Loren Hueter  
Nuclear Regulatory Commission  
Region III  
2443 Warrenville Road, Suite 210  
Lisle, Illinois 60522-4352


RE: Control No. 316579: An error (requiring issuance of a corrected copy) has been identified in License Condition 11. of recently issued new License Number 24-32674-01, dated October 10, 2007, to Midwest Cardiology Associates, P.C.

Dear Mr. Hueter:

In the telephone conversation with you, I related that the error involved designation of an Alternate Radiation Safety Officer, which is contrary to current NRC regulation, as specified in 10 CFR 35.24 (b) which specifies that a single individual (the designated Radiation Safety Officer) is to be responsible for implementing the licensee's radiation protection program.

License to request (please reference the request as additional information to Control No. 316579) that the position of Alternate Radiation Safety Officer be deleted from the subject license, by deletion of License Condition 11.B from License No. 24-32674-01. Please address response to "U.S. Nuclear Regulatory Commission, Region III; Materials Licensing Branch; 2443 Warrenville Road, Suite 210; Lisle, IL 60532-4352" and send it to my attention, by facsimile at 630-515-1078. No follow-up hard copy is needed. The license reviewer will then issue a corrected copy of the license, with the requested change, in order to meet the regulatory criteria as specified in 10 CFR 35.24(b). If you have questions, please call me at 913-253-3046 and Also please call right after you have sent response.

Thank you,



Stephen Bloom, M.D., FACP, FAHA, FASNC, FACC



## CONVERSATION RECORD

TIME DATE  
1-09-2008☐ VISIT ☐ CONFERENCE ☒ TELEPHONE☐ INCOMING  
☒ OUTGOING

## NAME OF PERSON(S) CONTACTED OR IN CONTACT

Stephen Bloom, M.D.  
Radiation Safety Officer

## ORGANIZATION (OFFICE, DEPT. ETC.)

Midwest Cardiology Associates, P.C.  
19550 E. 39<sup>th</sup> St., Suite 210  
Independence, MO 64057

## TELEPHONE NO.

913-253-3046  
FAX 913-663-2980

## SUBJECT

Control No. 316579: An error (requiring issuance of a corrected copy) has been identified in License Condition 11. of recently issued new License Number 24-32674-01, dated October 10, 2007, to Midwest Cardiology Associates, P.C.

## SUMMARY

In the telephone conversation, with Dr. Bloom, I related that the error involved designation of an Alternate Radiation Safety Officer, which is contrary to current NRC regulation, as specified in 10 CFR 35.24 (b) which specifies that a single individual (the designated Radiation Safety Officer) is to be responsible for implementing the licensee's radiation protection program.

## ACTION REQUIRED

Licensee to request (please reference the request as additional information to Control No. 316579) that the position of Alternate Radiation Safety Officer be deleted from the subject license, by deletion of License Condition 11. B. from License No. 24-32674-01. Please address response to "U.S. Nuclear Regulatory Commission, Region III; Materials Licensing Branch; 2443 Warrenville Road, Suite 210; Lisle, IL 60532-4352" and send it to my attention, by facsimile at 630-515-1078. No followup hard copy is needed. The license reviewer will then issue a corrected copy of the license, with the requested change, in order to meet the regulatory criteria as specified in 10 CFR 35.24(b). If you have questions, please call me at 630-829-9829 and Also please call right after you have sent response. Thank you.

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

Loren J. Hueter

1-09-2008

## ACTION TAKEN

SIGNATURE

TITLE

DATE

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this conversation record will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

NRC FORM 386 (R11)  
(4-2004)UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
2443 Warrenville Road, Suite 210  
Lisle, Illinois 60532-4352

## TELEFAX TRANSMITTAL

DATE:

1-9-08

NUMBER OF PAGES:

(including this page)

2

SEND TO:

Stephen Bloom, M.D.

LOCATION:

Midwest Cardiology

FAX NUMBER:

913-663-2980

VERIFY BY CALLING SENDER

FROM:

(SENDER)

Lynn Hester

TELEPHONE NUMBER:

630-829-9829

FAX NUMBER:

630-515-1078

If you do not receive the complete fax transmittal, please contact the sender as soon as possible at the telephone number provided above.

MESSAGE

## NOTICE

This message is intended only for the use of the individual or entity to which it is addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee responsible for delivering the message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately by telephone and return the original to the above address, by U.S. Mail. Thank you.