

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Honeywell International, Inc.
(System Sensors Incorporated Division)
St. Charles, IL
REPORT 2008-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4351

3. DOCKET NUMBER(S)

030-08445

4. LICENSEE NUMBER(S)

12-15023-02E

5. DATE(S) OF INSPECTION

Feb. 12, 2008

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura	Deborah A. Piskura	2/12/08

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE

Honeywell International, Inc.

REPORT NUMBER(S) 2008-001

2. NRC/REGIONAL OFFICE

Region III
2443 Warrenville Road
Lisle, IL 60532

3. DOCKET NUMBER(S)

030-08445

4. LICENSE NUMBER(S)

12-15023-02E

5. DATE(S) OF INSPECTION

Feb. 12, 2008

6. INSPECTION PROCEDURES

87111

7. INSPECTION FOCUS AREAS

03.01, 03.02, 03.03, 03.04, 03.05, 03.06, and 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM

03255

2. PRIORITY

E 5

3. LICENSEE CONTACT

Brian Langkin, RSO

4. TELEPHONE NUMBER

630.377.6674



Main Office Inspection

Next Inspection Date: Feb. 2013

Field Office _____



Temporary Job Site _____

PROGRAM SCOPE

This licensee was a manufacturer of commercial ionization smoke detectors, CO detectors and other devices and employed 700 individuals at its St. Charles, IL plant. The smoke detectors were directly distributed to building contractors for industrial use and installed in commercial buildings. The licensee manufactured approximately 180,000 ionization smoke detectors each year (140,000 detectors were distributed within the U.S.).

During this inspection, the inspector toured the manufacturing floor, interviewed licensee personnel, and reviewed select records including the licensees material transfer reports as required by 10 CFR 32.29(c).