NRC FORM 591M PART 1		U.S. NUCLEAR REGULATORY COMMISSION	
(10-2003) 10 CFR 2.201			
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
LICENSEE/LOCATION INSPECTED:		2. NRC/REGIONAL OFFICE	
Sinclair Wyoming Refining Company			
100 East Lincoln Highway Sinclair, Wyoming 82334		USNRC Region IV	
Location: Same		611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005	
		g, · · ·	
REPORT NUMBER(S) 2008-01			
3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION
030-37426 LICENSEE:	49-29255-01		2/11/2008
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X			
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)			
Licensee's Statement of Corrective Actions for Item 4, above.			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date			
LICENSEE'S	ieu ivallie	Signatur	e Date
REPRESENTATIVE			
NRC INSPECTOR R. Rie	ck Muñoz	1221	North 2/11/2008
ADAMS # MLO80660039 Template Date 3 / 6 / 08 QC'd by my			
		V	