

A-I and C-III

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

<p>1. LICENSEE</p> <p>Whittaker Corporation Nuclear Metals Division West Concord, Massachusetts 01781</p>	<p>2. REGIONAL OFFICE</p> <p>U. S. Atomic Energy Commission Region I, Division of Compliance 970 Broad Street Newark, New Jersey 07102</p>
<p>3. LICENSE NUMBER(S)</p> <p><u>SMB-65</u> and <u>SMB-179</u></p>	<p>4. DATE OF INSPECTION</p> <p>RI <u>May 13-14, 1971</u></p>
<p>5. INSPECTION FINDINGS</p> <p><input checked="" type="checkbox"/> A. No item of noncompliance was found.</p> <p><input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42</p> <p><input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42</p> <p><input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)</p> <p><input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)</p> <p><input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)</p> <p><input type="checkbox"/> G. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)</p> <p><input type="checkbox"/> H. Form AEC-3 was not properly posted. 10 CFR 20.206(c)</p> <p><input type="checkbox"/> I. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)</p> <p><input type="checkbox"/> J. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)</p> <p><input type="checkbox"/> K. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51</p> <p><input type="checkbox"/> L. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)</p> <p><input type="checkbox"/> M. Records of inventories were not maintained. 10 CFR 34.26</p> <p><input type="checkbox"/> N. Utilization logs were not maintained. 10 CFR 34.27</p> <p style="text-align: right;"><i>Raymond H. Smith</i> Raymond H. Smith, Radiation Specialist <i>(AEC Compliance Inspector)</i></p>	
<p>6. LICENSEE'S ACKNOWLEDGMENT</p> <p>The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.</p> <p>_____ (Date) _____ (Licensee Representative - Title or Position)</p>	

ORIGINAL: LICENSEE. COPIES: CO HEADQUARTERS CO ENFORCEMENT CO REGION

A114