CARDIAC TESTING CENTER 29 SOUTH STREET NEW PROVIDENCE NEW JERSEY 07974 (908-665-9500)

03022155

NNSBE

Licensing Assistant Section Nuclear Materials Safety Branch U.S. Nuclear Regulatory Commission, Region I 475 Allendale Road King of Prussia, PA 19406-1415

Re: Amendment NRC License # 29-20960-01 Decommissioning for Summit, NJ Office

February 20, 2008

Dear Sir/Madam:

Our NRC license 29-29060 has two facilities listed:

- 1) Cardiac Testing Center, 33 Overlook Road, Suite 305, Summit NJ
- 2) Cardiac Testing Center, 29 South Street, New Providence, NJ

We will be decommissioning <u>ONLY</u> our <u>Summit</u> nuclear medicine facility located at 33 Overlook Road, Suite 305, Summit, New Jersey 07901.

On February 20, 2008, our nuclear medicine pharmacy Del Med transportation logistics company (State Transporter Permit # 19752) transferred all of our radioactive sources from the Summit, NJ office to our hot lab at 29 South Street, New Providence, NJ for storage. All sources are within our possession limit.

Enclosed is the final wipe and survey of our Summit, New Jersey office. No removable contamination was detected.

Please remove authorize user, Alexander E. Kasatkin, M.D. from our license, he has permanently discontinued his duties.

Please contact our Physics Consultant, Elaine Rovazzi, M.S. @ (973) 322-5118 for any further information.

Sinceret M. D. Fam

Management

Enc. Decommissioning survey report for Summit, NJ office

141230

NMSS/RGN1 MATERIALS-002

ട്ടുണ്ട് 3 2 ... 640

Michael Tighe, M.D./RSO Cardiac Testing Center 29 South Street New Providence, NJ 07947

NJBRP License #20295-01 (Summit office ONLY) NRC License #29-20960

DECOMMISSIONING SURVEY NUCLEAR MEDICINE February 20, 2008

Area Survey

Locations surveyed:	1.	Hot Lab/ Scanning Area/Stress lab		
Instrument:		Ludlum Model 14-C Serial # <u>105296</u> Pancake Probe Model 44-9 109186 Calibration Date - <u>5/1/07</u> (Check Source: 3.7 mR/hr) Check Source Reading <u>3.7 mR/hr</u>		
Background:		Less than 0.02 mR/hr		
Actual Readings:	All areas were less than 0.02 mR/hr			
Area Wipe Test				
Locations surveyed:	1.	Hot Lab/ Scanning Room/Stress Lab		
Instrument:		Ludium 2000 Nai Well Co Serial # <u>102755</u> Efficiency for ¹³⁷ Cs: MDA for 1 min:	33.4%	
Background:		510 cpm		
Results:	1. 2. 3.	Scanning Room - Stress Room -		

Decommissioning Results:	No radiation detected in any area
Claure Rovanius	Ort <i>3R</i> February 20, 200

February 20, 2008 Date

Elaine Rovazzi, M.S., D.A.B.R. Board Certified: American Board of Radiology Michael Tighe, M.D./RSO Cardiac Testing Center 29 South Street New Providence, NJ 07947

NJBRP License #20295-01 (Summit office ONLY) NRC License #29-20960

DECOMMISSIONING SURVEY NUCLEAR MEDICINE February 20, 2008

Area Survey

Locations surveyed:	1.	Hot Lab/ Scanning Area/Stress lab		
Instrument:		Ludlum Model 14-C Serial #105296 Pancake Probe Model 44-9 109186 Calibration Date5/1/07 (Check Source: 3.7 mR/hr) Check Source Reading <u>3.7 mR/hr</u>		
Background:		Less than 0.02 mR/hr		
Actual Readings:	All areas	areas were less than 0.02 mR/hr		
Area Wipe Test				
Locations surveyed:	1.	Hot Lab/ Scanning Room/Stress Lab		
Instrument:		Ludlum 2000 Nal Well Counter Model Serial # <u>102755</u>		
		Efficiency for ¹³⁷ Cs:	33.4%	
			0.000051 uCi	
Background:		510 cpm		
Results:	1. 2. 3.	Hot Lab - Scanning Room - Stress Room - ALL AREAS WITHIN STAT	513 cpm (9 dpm)	

Decommissioning Results: No radiation detected in any area

Claun Rovazzi MS DABR Elaine Rovazzi, M.S., D.A.B.R.

American Board of Radiology

Board Certified:

February 20, 2008 Date This is to acknowledge the receipt of your letter/application dated $\frac{1}{2} \frac{1}{2} \frac{1}{3} \frac{1}{3}$ includes an administrative review has been performed.

, ·

There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number ________ When calling to inquire about this action, please refer to this control number. You may call us on (610) 337-5398, or 337-5260.

NRC FORM 532 (RI) (6-96)

Sincerely, Licensing Assistance Team Leader