NRC FORM 591M PART (10-2003) 10 CFR 2.201				U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
1. LICENSEE/LOCATION INSPECTED: The Cardiology Group 111 Northfield Avenue West Orange, NJ 07052  REPORT Nos 2007-001			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415			
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S	·	5. DATE(S) OF INSPECTION		
03033828		29-30214-	4-01 October 31, 2007		0+	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X						
Licensee's Statement of Corrective Actions for Item 4, above.  I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.  Title Printed Name Signature Date						
LICENSEE'S REPRESENTATIVE						
NRC INSPECTOR	Michelle Si	immons	Muhelte	Simmos	10/3/07	
NRC FORM 591M PART	1 (Rev. by RI 07/06)		G:\Doss\Current\Insp Re	cord\R29-30214-01.2007-00	1.591M-Part1.wpd	

SUNSI Review Completed By: /RA/ Michelle Simmons X Public X Non-Sensitive