NRC FORM 591M PART 1 (10-2003)		U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
LICENSEE/LOCATION INSPECTED:     Summit Medical Group, P.A.     Diamond Hill Road     Cardiology Department, Bensley Pavilion, 2nd Floor     Berkeley Heights, NJ 07922  REPORT Nos 2008-001		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
REPORT Nos 2008-001  3. DOCKET NUMBER(S)	4. LICENSE NUMBER(	8)	5. DATE(S) OF INSPEC	TION
030-09678	29-15739-01	0)	January 17, 2	
LICENSEE:			1111	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X				
Licensee's Statement of Corrective Actions for Item 4, above.  I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.				
·	inted Name		nature	Date
LICENSEE'S REPRESENTATIVE	-	1.	f	
NRC INSPECTOR Michelle S	Simmons	Michelle	Simmon	1/17/08
NRC FORM 591M PART 1 (Rev. by RI 07/06)		G:\Docs\Current\Insp Rec		01.591M-Part1.wpd

SUNSI Review Completed By:

/RA/

Michelle SImmons

X Public

X Non-Sensitive