NRC FORM 591M PART 3		U	S. NUCLEAR REGULATORY COMMISSION						
(10-2003) 10 CFR 2.201	Docket File Information								
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE 2. NRC/REGIONAL OFFICE									
Mount Clemens Regional Med Ctr		Region III 2443 Warrenville Road							
REPORT NUMBER(S) 2008-001 3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	Lisie, IL 60532	5. DATE(S) OF INSPECTION						
030-04080	21-04080-01		3/6/08						
6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS								
87131 03.01-03.07 SUPPLEMENTAL INSPECTION INFORMATION									
1. PROGRAM CODE(S) 2. PRIORITY	3. LICENSEE CONTACT		4. TELEPHONE NUMBER						
2230 2	Arthur Frazier	·	313/466-8090						
X Main Office Inspection Next Inspection Date: 4/2010									
Field Office			_						
Temporary Job Site									
	PROGRA	M SCOPE							
Licensee is a regional hospital	located in Mt. Cl	amens Michigan (no	orth of Detroit) Licensee						
Licensee is a regional hospital located in Mt. Clemens, Michigan (north of Detroit). Licensee has a moderate sized nuclear medicine program conducting a host of procedures. The									
receives its radiopharmaceutica	als in the form of	unit doses from Mal	linckrodt and occasional						
has a moderate sized nuclear medicine program conducting a host of procedures. The licensee has four techs who perform approximately 20 procedures per day. This hospital receives its radiopharmaceuticals in the form of unit doses from Mallinckrodt and occasional doses from G. E. Health. This licensee performs cardiac stress studies, diagnostic iodine procedures, bone studies, gastric studies and other work using licensed materials.									
bone suules, yastile suules and other work using ileensed materials.									
Performance Observations									
The inspector toured the facilities and interviewed authorized users and staff members. Each appeared knowledgeable in radiation safety and radionuclide handling techniques. Licensee personnel demonstrated package receipt procedures for the inspector. Staff members also demonstrated proper									
demonstrated package receipt procedures for the inspector. Staff members also demonstrated proper									
rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.									
The inspector observed members of the nuclear medicine staff perform injections of licensed materials.									
Techniques employed by the staff knowledge of radiation safety. Du	demonstrated goo Iring the course of	od handling practices the inspection, no abr	as well as an adequate normalities were noted.						
Licensee has added a HDR unit to its procedures listing since the last inspection. The inspector reviewed daily check of equipment and written directives for the treatments delivered by HDR. Checks of equipment and training of staff were adequate. No errors were observed in the written directives									
reviewed.	re adequate. No	errors were observed	in the written directives						

NRC FORM 591M PART 3 (10-2003)

NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201									
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSE ELOCATION INSPECTED: Mount Clemens Regional Medical Center 1000 Harrington Blud Mt. Clemens, MI 4864) REPORT NUMBER(S)2008001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351							
3. DOCKET NUMBER	S)	4. LICENSEE NUM				ION			
O3D-02040		21-04080-01		Mar 6,2008					
 LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 1. Based on the inspection findings, no violations were identified. 2. Previous violation(s) closed. 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self- 									
identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG- 1600, to exercise discretion, were satisfied.									
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): A. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)									
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,									
corrective actions is made in date when full compliance Title	will be achieved). I	e requirements of 10 CFR understand that no furthe nted Name	r written response to NRC w	ady taken, corrective steps v ill be required, unless specifi Inature	ically	vill be taken, requested. Date			
LICENSEE'S REPRESENTATIVE									
NRC INSPECTOR	G. Park	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	THE		3	6 0%			

NRC FORM 591M PART 1 (10-2003)