



Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, N.Y. 10511-0249
Tel (914) 734-6700

Fred Dacimo
Vice President License Renewal

April 28, 2008
Indian Point Unit Nos. 2 and 3
NL-08-071

Mr. Andrew Feeney
First Deputy Director
New York State Emergency Management Office
1220 Washington Avenue
Public Security Building 22
Albany, New York 12226-2251

Subject: Response to FEMA Request for Additional Information on the Failure Modes and Effects Analysis of the Indian Point Energy Center Siren System

Reference: FEMA letter, "Indian Point Energy Center Alert and Notification System Design Report, specifically the Failure Modes and Effects Analysis (FMEA)," dated April 7, 2008


Dear Mr. Feeney:

Entergy Nuclear Operations, Inc. (Entergy) hereby submits the enclosed response to the Federal Emergency Management Agency (FEMA) request for additional information on the Failure Modes and Effects Analysis (FMEA) Report of the Indian Point Energy Center (IPEC) siren system. This submittal is being provided in response to the referenced letter.

Entergy requests that the attachments to this letter be exempt from public disclosure. The attachments contain proprietary information and are provided with the understanding the information will not be available to the public.

Should you have any questions regarding this matter, please contact Mr. Michael J. Slobodien, Director Emergency Planning, Entergy at (914) 272-3352.

Sincerely yours,


Fred R. Dacimo
Vice President License Renewal
Indian Point Energy Center

- Attachment: 1. Response to FEMA Request for Additional Information on the Failure Modes and Effects Analysis of the Indian Point Energy Center Siren System.
- Attachment: 2. FMEA of the New Siren System for IPEC Report IP-RPT-08-00005, Revision 1.
- Attachment: 3. Entergy Policy EN-PL-155 (partial)
- Attachment: 4. Condition Report LO-IP3LO-2007-00326 (partial)
- Attachment: 5. FMEA Major RPN Reductions
- Attachment: 6. FMEA Sample Matrix of Corrective Action Assignments
- Attachment: 7. Example of Routine Test and Inspection Procedures
- IP-EP-AD32 Revision 0
 - IP-EP-AD33 Revision 0
- Attachment: 8. Procedure IP-EP-AD32 Summary and Goals

cc: next page

cc: Document Control Desk (w/o Attachments)
U.S. Nuclear Regulatory Commission
Mail Stop O-P1-17
Washington, DC 20555-0001

Mr. Samuel J. Collins (w/o Attachments)
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

Resident Inspector's Office (w/o Attachments)
Indian Point Unit Nos. 2 and 3
U.S. Nuclear Regulatory Commission

Mr. Robert Kahler (w/o Attachments)
Office of Nuclear Security and Incident Response
Division of Preparedness and Response
Licensing and Inspection Branch
Nuclear Regulatory Commission
Two White Flint North MS T3B46M
11545 Rockville Pike
Rockville, MD 20852

Ms. Rebecca S. Thompson (w/Attachments)
REP Branch Chief
Federal Emergency Management Agency
Region II
26 Federal Plaza, 13th Floor, Suite 1337
New York, NY 10278-0002

Mr. Stephen Kempf, Jr. (w/o Attachments)
Regional Administrator
Federal Emergency Management Agency
Region II
26 Federal Plaza
New York, NY 10278

Mr. Daniel Greeley (w/o Attachments)
Deputy Director
Rockland County Fire and Emergency Services
35 Fireman's Memorial Drive
Pomona, New York 10970

Mr. Anthony Sutton (w/o Attachments)
Commissioner
Westchester County
Department of Emergency
Services
4 Dana Road
Valhalla, New York 10595

Mr. Seamus Leary (w/o Attachments)
Deputy Commissioner
Orange County
Department of Emergency
Services
225 Main Street
Goshen, New York 10924

Mr. Adam Stiebeling (w/o Attachments)
Deputy Commissioner
Putnam County
Bureau of Emergency Services
112 Old Route 6
Carmel, New York 10512

Mr. Paul Eddy
Public Service Commission
NYS – Department of Public
Service (w/o Attachments)
3 Empire State Plaza
Albany, NY 12223