

NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Atlantic Medical Imaging
Stockton Medical Building, Suite 1100
72 W. Jimmie Leeds Rd, Galloway, NJ 08205

REPORT Nos 2008001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region 1, 475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

3. DOCKET NUMBER(S)
03031206

4. LICENSE NUMBER(S)
29-28395-01

5. DATE(S) OF INSPECTION
March 19-20 & April 10, 2008

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10CFR 35.61 requires, in part, that a licensee shall (a) calibrate the survey instruments used to show compliance with 10 CFR Parts 20 and 35 before first use, annually, and following a repair that affects the calibration, and (c) shall retain a record of each survey instrument calibration in accordance with 10CFR 35.2061. 10CFR 20.1501(b) requires the licensee shall ensure that instruments and equipment used for quantitative radiation measurements (e.g., dose rate and effluent monitoring) are calibrated periodically for the radiation measured. (Continued on next page)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	JONATHAN LAW		4/22/08
NRC INSPECTOR	Todd J. Jackson, CHP		4/22/08

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Atlantic Medical Imaging Stockton Medical Building, Suite 1100 72 W. Jimmie Leeds Rd, Galloway, NJ 08205		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2008001			
3. DOCKET NUMBER(S) 03031206	4. LICENSE NUMBER(S) 29-28395-01	5. DATE(S) OF INSPECTION March 19-20 & April 10, 2008	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:


- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10CFR 35.61 requires, in part, that a licensee shall (a)calibrate the survey instruments used to show compliance with 10 CFR Parts 20 and 35 before first use, annually, and following a repair that affects the calibration, and (c)shall retain a record of each survey instrument calibration in accordance with 10CFR 35.2061. 10CFR 20.1501(b) requires the licensee shall ensure that instruments and equipment used for quantitative radiation measurements (e.g., dose rate and effluent monitoring) are calibrated periodically for the radiation measured. (Continued on next page)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Todd J. Jackson, CHP		4/22/08