

NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION		
	ETY INSPECTION REPO	ORT AND COMP	LIANCE INSPECTION	ON
1. LICENSEE/LOCATION INSPECT	2. NRC/REGION	2. NRC/REGIONAL OFFICE		
Nowak & Fraus, L.L. 46777 Woodward Av Pontiac, MI 48342-50	Region II	U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210		
REPORT NUMBER(S)		Lisle, Illinois 60532-4351		
3. DOCKET NUMBER(S) 030-31487	4. LICENSEE 21-2	NUMBER(\$) 6122-01	5. DATE(S)	OF INSPECTION 2008
LICENSEE:				
to compliance with the Nuclear The inspection consisted cand observations by the in 1. Based on the inspect 2. Previous violation(s) 3. The violation(s), spec	rifically described to you by the insp	n (NRC) rules and reprocedures and reprings are as follows stiffed.	regulations and the co presentative records, in s: ations, are not being cited be	nditions of your license. Iterviews with personnel,
1600, to exercise discret			-	•
No	n-Cited Violation(s) was/were discu	issed involving the follo	owing requirement(s) and Co	rrective Action(s):
	, and the second	e subject to posting in a	accordance with 10 CFR 19.	
I haraby state that within 00 de	Licensee's Statement of (dentified The state of
corrective actions is made in acc	lys, the actions described by me to ordance with the requirements of 10 be achieved). I understand that no the Printed Name	CFR 2.201 (corrective	steps already taken, correct	tive steps which will be taken.
LICENSEE'S REPRESENTATIVE	r miled ivaline	X	Signature	Date
NRC INSPECTOR	Robert P. Hays	T)	V X ton	5/1/08
NRC FORM 591M PART 1 (10-2003)				

NRC FORM 591M (10-2003) 10 CFR 2.201	PART 3	Docket File Information SAFETY INSPECTION RE AND COMPLIANCE INSPE	PORT		
1. LICENSEE Nowak & Fraus REPORT NUMBER(S)	s, L.L.C. 2008-001	2. NRC/REGION Region II	NAL OFFICE II rrenville Road, Suite 210		
3. DOCKET NUMBER(S) 03031487		4. LICENSE NUMBER(S) 21-26122-01	5. DATE(S) OF INSPECTION May 1, 2008		
6. INSPECTION PROCEDURES USED 87124 (11/25/03)		7. INSPECTION FOCUS AREAS 03.01-03.07			
		SUPPLEMENTAL INSPECTION INFO	RMATION		
1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Chad Findley, RSO	4. TELEPHONE NUMBER 248-332-7931		
X Main Office Inspection Next Inspection Date: May 2013					
X Field Office 1310 North Stephenson Highway, Royal Oak, MI					
Temporary Job Site Inspection					

PROGRAM SCOPE

The licensee is authorized to possess and use portable moisture density gauges at temporary job sites anywhere in the United States where the NRC maintains regulatory jurisdiction. The license has 5 employees qualified to use portable moisture gauges at temporary jobsites in Michigan. The gauges are used infrequently and are not stored at temporary job sites or at an employee's residence. At the time of the inspection, no gauges were being used at a temporary job site.

Performance Observations

During the inspection, the inspector reviewed and discussed with the RSO: (1) Two tangible barriers required for gauge security and padlocks, (2) DOT requirements, hazmat recertification and tests; (3) refresher training for gauge users; (4) dosimetry and records; (5) leak tests and inventories; (6) security of licensed material at each authorized storage facility; (7) survey meter availability; and (8) emergency procedures;

No violations were identified. The inspection also determined that the licensee had implemented corrective actions for a previous SL IV violation pertaining to locking the gauge handle and transport case and now considered closed.