

June 17, 2008

Mr. J. Randy Johnson  
Vice President - Farley  
Joseph M. Farley Nuclear Plant  
7388 North State Highway 95  
Columbia, AL 36319

SUBJECT: JOSEPH M. FARLEY NUCLEAR PLANT, UNIT NOS. 1 & 2, WITHDRAWAL OF  
RELIEF REQUEST FOR TEMPORARY NON-CODE REPAIR OF SERVICE  
WATER PIPING (TAC NOS. MD6746 AND MD6747)

Dear Mr. Johnson

By letter dated May 11, 2006, to the U.S. Nuclear Regulatory Commission, Agencywide Document Access System (ADAMS) Accession No. ML061310494, and September 10, 2007 (Accession No. ML072540429), Southern Nuclear Operating Company, Inc. submitted requests to allow temporary non-code repairs of through wall pinhole leaks in service water piping downstream of Unit 1, Q1P16V510 and Unit 2, Q2P16V510 respectively.

The requests were subsequently withdrawn in letters dated December 21, 2007 (ADAMS Accession No. ML073550639) and January 11, 2008 (ADAMS Accession No. ML080140218) where it was identified that the leaks were repaired during Joseph M. Farley Nuclear Plant Outages 1R21 and 2R18.

This letter acknowledges the withdrawal and concludes the work performed on the requests.

Sincerely,

**/RA/**

R. A. Jervy, Project Manager  
Plant Licensing Branch II-1  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket Nos. 50-348 and 50-364

cc: See next page

June 17, 2008

Mr. J. Randy Johnson  
Vice President - Farley  
Joseph M. Farley Nuclear Plant  
7388 North State Highway 95  
Columbia, AL 36319

SUBJECT: JOSEPH M. FARLEY NUCLEAR PLANT, UNIT NOS. 1 & 2, WITHDRAWAL OF RELIEF REQUEST FOR TEMPORARY NON-CODE REPAIR OF SERVICE WATER PIPING (TAC NOS. MD6746 AND MD6747)

By letter dated May 11, 2006, to the U.S. Nuclear Regulatory Commission, Agencywide Document Access System (ADAMS) Accession No. ML061310494, and September 10, 2007 (Accession No. ML072540429), Southern Nuclear Operating Company, Inc. submitted requests to allow temporary non-code repairs of through wall pinhole leaks in service water piping downstream of Unit 1 Q1P16V510 and Unit 2, Q2P16V510 respectively.

The requests were subsequently withdrawn in letters dated December 21, 2007 (ADAMS Accession No. ML073550639) and January 11, 2008 (ADAMS Accession No. ML080140218) where it was identified that the leaks were repaired during Joseph M. Farley Nuclear Plant Outages 1R21 and 2R18.

This letter acknowledges the withdrawal and concludes the work performed on the requests.

Sincerely,

**/RA/**

R. A. Jervey, Project Manager  
Plant Licensing Branch II-1  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket Nos. 50-348 and 50-364

cc: See next page

Distribution:

Public	RidsAcrsAcnw&mailCenter	RidsNrrPMRJervey
LPL2-1 R/F	RidsNrrDorlDpr	RidsNrrDorlLpl2-1
RidsOgcRp	RidsNrrDirsltsb	RidsNrrLAGLappert
RidsRgn2MailCenter		

ADAMS Accession No.: ML081660002

NRR-028

OFFICE	NRR/LPL2-1/PM	NRR/LPD2-1/LA	NRR/LPL2-1/BC
NAME	RJervey	GLappert	MWong
DATE	6/17/08	6/17/08	6/17/08

**OFFICIAL RECORD COPY**

Joseph M. Farley Nuclear Plant, Units 1 & 2

cc:

Mr. J. Randy Johnson  
Vice President - Farley  
Joseph M. Farley Nuclear Plant  
7388 North State Highway 95  
Columbia, AL 36319

Mr. B. D. McKinney, Licensing Manager  
Southern Nuclear Operating Company, Inc.  
P.O. Box 1295  
Birmingham, AL 35201-1295

Mr. M. Stanford Blanton  
Balch and Bingham Law Firm  
P.O. Box 306  
1710 Sixth Avenue North  
Birmingham, AL 35201

Mr. J. Gasser  
Executive Vice President  
Southern Nuclear Operating Company, Inc.  
P.O. Box 1295  
Birmingham, AL 35201

State Health Officer  
Alabama Department of Public Health  
434 Monroe St.  
Montgomery, AL 36130-1701

Chairman  
Houston County Commission  
P.O. Box 6406  
Dothan, AL 36302

Resident Inspector  
U.S. Nuclear Regulatory Commission  
7388 N. State Highway 95  
Columbia, AL 36319

William D. Oldfield  
SAER Supervisor  
Southern Nuclear Operating Company, Inc.  
P.O. Box 470  
Ashford, AL 36312