

## CCNPP3COLA PEmails

---

**From:** Joseph Colaccino  
**Sent:** Thursday, June 12, 2008 10:27 AM  
**To:** John Rycyna  
**Cc:** CCNPP3COL Resource  
**Subject:** FW: Turbine building vent system

John,

Below is an external communication from Areva concerning coordination of the DC and COL application content.

Thanks, Joe.

---

**From:** MCINTYRE Brian (AREVA NP INC) [mailto:Brian.McIntyre@areva.com]  
**Sent:** Tuesday, June 10, 2008 11:24 AM  
**To:** Joseph Colaccino  
**Cc:** MCINTYRE Brian (AREVA NP INC)  
**Subject:** Turbine building vent system

Joe,

I am out of the office, but it is my understanding that John Rycyna called John Price to give a heads up on the "lack of coordination calls" calls to Tom and George V. One of the issues mentioned is the turbine building ventilation system. Areva is unaware of any issues with this nonsafety system in a nonsafety building. Is there a communication that I missed.

As this is, I am surprised. I thought we had agreed no surprises.

What am I missing here?

The other items were the fuel racks and the layout, both of which we have had dialog on.

Brian A. McIntyre

**Hearing Identifier:** CalvertCliffs\_Unit3Cola\_Public\_EX  
**Email Number:** 39

**Mail Envelope Properties** (3AF7DEF82ADA8944AD8247B7ED7FD65157030DD71B)

**Subject:** FW: Turbine building vent system  
**Sent Date:** 6/12/2008 10:27:29 AM  
**Received Date:** 6/12/2008 10:27:31 AM  
**From:** Joseph Colaccino

**Created By:** Joseph.Colaccino@nrc.gov

**Recipients:**  
"CCNPP3COL Resource" <CCNPP3COL.Resource@nrc.gov>  
Tracking Status: None  
"John Rycyna" <John.Rycyna@nrc.gov>  
Tracking Status: None

**Post Office:** HQCLSTR01.nrc.gov

<b>Files</b>	<b>Size</b>	<b>Date &amp; Time</b>
MESSAGE	956	6/12/2008 10:27:31 AM

**Options**  
**Priority:** Standard  
**Return Notification:** No  
**Reply Requested:** No  
**Sensitivity:** Normal  
**Expiration Date:**  
**Recipients Received:**