

July 10, 2008

Vice President, Operations
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, NY 10511-0249

SUBJECT: AUDIT REPORT FOR THE CORRECTIVE ACTIONS ASSOCIATED WITH
GENERIC LETTER 2004-02 (TAC NOS. MC4689 AND MC4690)

Dear Sir or Madam:

During the week of December 3, 2007, the Nuclear Regulatory Commission (NRC) staff conducted a detailed audit of the new sump designs at Indian Point Nuclear Generating Unit Nos. 2 and 3, operated by Entergy Nuclear Operations, Inc. (Entergy). The audit focused on Entergy's corrective actions related to NRC Generic Letter (GL) 2004-02, "Potential Impact of Debris Blockage on Emergency Recirculation During Design Basis Accidents."

Pursuant to Section 2.390 of Title 10 of the *Code of Federal Regulations* (10 CFR), our initial determination is that the enclosed audit report does not contain proprietary information. However, we will delay placing the audit report in the public document room for a period of 2 weeks from the date of this letter to provide you with the opportunity to comment on any proprietary aspects. If you believe that any information in the enclosure is proprietary, please identify such information line-by-line and define the basis pursuant to the criteria of 10 CFR 2.390. After 2 weeks, the audit report will be made publicly available after making any necessary changes to remove proprietary information.

To facilitate the NRC staff's review of your comments, please provide a marked-up copy of the audit report showing proposed changes and provide a summary table of the proposed changes. If you have any questions, please contact me at 301-415-2901.

Sincerely,

/ra/

John P. Boska, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-247 and 50-286

Enclosure:
Audit Report

cc w/o encl: See next page

July 10, 2008

Vice President, Operations
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, NY 10511-0249

SUBJECT: AUDIT REPORT FOR THE CORRECTIVE ACTIONS ASSOCIATED WITH
GENERIC LETTER 2004-02 (TAC NOS. MC4689 AND MC4690)

Dear Sir or Madam:

During the week of December 3, 2007, the Nuclear Regulatory Commission (NRC) staff conducted a detailed audit of the new sump designs at Indian Point Nuclear Generating Unit Nos. 2 and 3, operated by Entergy Nuclear Operations, Inc. (Entergy). The audit focused on Entergy's corrective actions related to NRC Generic Letter (GL) 2004-02, "Potential Impact of Debris Blockage on Emergency Recirculation During Design Basis Accidents."

Pursuant to Section 2.390 of Title 10 of the *Code of Federal Regulations* (10 CFR), our initial determination is that the enclosed audit report does not contain proprietary information. However, we will delay placing the audit report in the public document room for a period of 2 weeks from the date of this letter to provide you with the opportunity to comment on any proprietary aspects. If you believe that any information in the enclosure is proprietary, please identify such information line-by-line and define the basis pursuant to the criteria of 10 CFR 2.390. After 2 weeks, the audit report will be made publicly available after making any necessary changes to remove proprietary information.

To facilitate the NRC staff's review of your comments, please provide a marked-up copy of the audit report showing proposed changes and provide a summary table of the proposed changes. If you have any questions, please contact me at 301-415-2901.

Sincerely,

/ra/

John P. Boska, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-247 and 50-286

Enclosure:

Audit Report

cc w/o encl: See next page

DISTRIBUTION:

See next page

ADAMS Accession Number: ML081820036

OFFICE	LPL1-1/PM	LPL1-1/LA	LPL1-1/BC
NAME	JBoska	SLittle	MKowal
DATE	7/10/08	7/10/08	7/10/08

OFFICIAL RECORD COPY

DATED:

SUBJECT: AUDIT REPORT FOR THE CORRECTIVE ACTIONS ASSOCIATED WITH
GENERIC LETTER 2004-02 (TAC NOS. MC4689 AND MC4690)

DISTRIBUTION:

LPL1-1 R/F

RidNrrDorl

RidsNrrDorlLpl1-1

RidsNrrDorlDpr

RidsNrrDirsltsb

RidsNrrPMJBoska

RidsNrrPMDPickett

RidsNrrLASLittle (paper copy)

RidsRgn1MailCenter

Indian Point Nuclear Generating Unit Nos. 2 and 3

cc:

Senior Vice President
Entergy Nuclear Operations, Inc.
P.O. Box 31995
Jackson, MS 39286-1995

Vice President Oversight
Entergy Nuclear Operations, Inc.
P.O. Box 31995
Jackson, MS 39286-1995

Senior Manager, Nuclear Safety & Licensing
Entergy Nuclear Operations, Inc.
P.O. Box 31995
Jackson, MS 39286-1995

Senior Vice President and COO
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Assistant General Counsel
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Manager, Licensing
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, NY 10511-0249

Mr. Paul Tonko
President and CEO
New York State Energy, Research, and
Development Authority
17 Columbia Circle
Albany, NY 12203-6399

Mr. John P. Spath
New York State Energy, Research, and
Development Authority
17 Columbia Circle
Albany, NY 12203-6399

Mr. Paul Eddy
New York State Department
of Public Service
3 Empire State Plaza
Albany, NY 12223-1350

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Senior Resident Inspector's Office
Indian Point 2 and 3
U. S. Nuclear Regulatory Commission
P.O. Box 59
Buchanan, NY 10511

Mr. Charles Donaldson, Esquire
Assistant Attorney General
New York Department of Law
120 Broadway
New York, NY 10271

Mr. Raymond L. Albanese
Four County Coordinator
200 Bradhurst Avenue
Unit 4 Westchester County
Hawthorne, NY 10532

Mayor, Village of Buchanan
236 Tate Avenue
Buchanan, NY 10511

Mr. Jim Riccio
Greenpeace
702 H Street, NW
Suite 300
Washington, DC 20001

Mr. Phillip Musegaas
Riverkeeper, Inc.
828 South Broadway
Tarrytown, NY 10591

Mr. Mark Jacobs
IPSEC
46 Highland Drive
Garrison, NY 10524

Mr. Sherwood Martinelli
FUSE USA
via email