

**Vogtle Electric Generating Plant Units 1 and 2
License Amendment Request to Revise Technical Specification (TS)
Sections 5.5.9, "Steam Generator (SG) Program" and TS 5.6.10,
"Steam Generator Tube Inspection Report" for Interim Alternate Repair Criterion**

Enclosure 10

**GP-18283, "Transmittal of Document – LTR-CDME-08-25, 'Errata for LTR-CDME-08-11;
Interim Alternate Repair Criterion (ARC) for Cracks in the Lower Region of the Tubesheet
Expansion Zone,' " dated February 12, 2008**

Westinghouse Proprietary Class 2



Westinghouse Electric Company
Nuclear Services
P.O. Box 355
Pittsburgh, Pennsylvania 15230-0355
USA

Mr. T. E. Tynan
Vice President, Nuclear Vogtle Project
Southern Nuclear Operating Company, Inc.
Vogtle Electric Generating Plant
7821 River Road
Waynesboro, GA 30830

Direct tel: (412) 374-3365
Direct fax: (412) 374-3451
e-mail: ArnoldEC@westinghouse.com
Our ref: GP-18283

February 12, 2008

**SOUTHERN NUCLEAR OPERATING COMPANY
VOGTLE ELECTRIC GENERATING PLANT UNITS 1 AND 2
Transmittal of Document – LTR-CDME-08-25 “Errata for LTR-CDME-08-11; Interim Alternate
Repair Criterion (ARC) for Cracks in the Lower Region of the Tubesheet Expansion Zone”**

Dear Mr. Tynan:

This letter transmits LTR-CDME-08-25, “Errata for LTR-CDME-08-11; Interim Alternate Repair Criterion (ARC) for Cracks in the Lower Region of the Tubesheet Expansion Zone” dated January 31, 2008. This letter is being issued to address comments that were received on the initial transmittal (GP-18280).

If you have any questions regarding this transmittal, please contact Jon Barkich at (724) 722-5239 or myself at (412) 374-3365.

Very truly yours,

A handwritten signature in cursive script that reads "E. C. Arnold".

E. C. Arnold, Manager
Southern Nuclear Projects

Westinghouse Proprietary Class 2

Page 2
Our ref: GP-18283
February 12, 2008

cc: R.H. Parker
R.S. Cowman
J.L. Tain
J.C. Robinson
P.M. Conley
C.R. Dedrickson
T.L. Youngblood
J.D. Williams
W.C. Moore
R.E. Mullins

Westinghouse Proprietary Class 2

Page 3
Our ref: GP-18283
February 12, 2008

bcc: H.O. Lagally
C.E. Cassino
J.T. Kandra
G.W. Whiteman
J.L. Barkich
E.C. Arnold
G.E. Gontis



To: P. J. McDonough
D. Alexander
E. Arnold

Date: February 12, 2008

cc: G.W. Whiteman
E. P. Morgan

J. A. Gresham

From: H.O. Lagally
Ext: 724-722-5082
Fax: 724-722-5909

Your ref:
Our ref: LTR-CDME-08-25

Subject: **Errata for LTR-CDME-08-11; "Interim Alternate Repair Criterion (ARC) for Cracks in the Lower Region of the Tubesheet Expansion Zone"**

The subject letter report, issued on January 31, 2008 to Wolf Creek Nuclear Operating Company for Wolf Creek, and subsequently again to Southern Nuclear Company for Vogtle Units 1 and 2 and to EXELON for Braidwood Unit 2 and Byron Unit 2, contains typographical errors in Section 5 of the report. In Section 5, all reference to Figures, Tables and References refer to section 6 which was removed from the report; all of the references to Figures, Tables and References should refer to section 5 of the report.

Author: *HOL*
H.O. Lagally
Chemistry, Diagnostics
and Materials Engineering

Verified: *CDC*
C.D. Cassino
Chemistry, Diagnostics
and Materials Engineering