

#### BASIN ELECTRIC POWER COOPERATIVE

1717 EAST INTERSTATE AVENUE BISMARCK, NORTH DAKOTA 58503-0564 PHONE 701-223-0441 FAX: 701/224-5336 RECEIVED

JUN 1 3 2008

DNMS

5

May 9, 2008

James L. Montgomery Nuclear Materials Safety Branch B United States Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011-4005

SUBJECT: AMENDMENT TO NRC LICENSE No. 33-18224-01

Dear Mr. Montgomery:

This letter is to provide notice of a new Radiation Safety Officer for the facility named in the license, as Mr. Terry Archbold has retired. Therefore the following request is made to change Condition 12.A. to read as follows:

"The Radiation Safety Officer for this license is David Cummings."

Mr. Cummings has successfully met the criteria described in Condition 12.B., and has previously served as RSO for the Western Sugar Cooperative, Torrington, WY for the time period of May 2006 through February 2008. In addition, he will be attending refresher training within the near future. Attached is a copy of his current certificate.

Also, Amendment No. 09 to License No. 33-18224-01 was issued March 31, 2008. Item 8.B. states that the maximum amount that we may posses is 1 curie total. No single source to exceed 250 millicuries. However, one Model 5190 has an activity of 1 curie and the total for Model 5190 devices is 1.3 curies. Please correct the license accordingly.

Please do not hesitate to contact me with any questions. My phone number is 701-355-5654 and my email is beriksen@bepc.com.


Sincerely,

about 2 Sinks

Robert L. Eriksen, P.E. Sr. Environmental Compliance Administrator

attach.

h



1

# **David Cummings**

Â

Has successfully completed the Technical Short Course entitled

## **Radiation Safety Officer**

May 15 - 19, 2006

Presented in Las Vegas, Nevada this 19th day of May 2006

By Nevada Technical Associates, Inc.

Approved for 30.5 CD credits from the American Society of Radiologic Technologists

Robert Holloway, Ph.D Course Coordinator

3

SAR

SÂP

### ACCEPTANCE REVIEW MEMO (ARM)

Licensee:	Basin Electric Power Cooperative	License No.: 33-18224-01
Docket No.:	030-14682	Mail Control No.: 471839
Type of Action:	Amend	Date of Requested Action: 05-09-08
Reviewer Assigned:		ARM reviewer(s): J. Cook

Response	Deficiencies Noted During Acceptance Review	
	<ul> <li>[X] Open ended possession limits. Submit inventory. Limit possession.</li> <li>[] Submit copies of latest leak test results.</li> <li>[] Add IC L.C./Fingerprint LC, add SUNSI markings to license.</li> <li>[] Confirm with licensee if they have NARM material.</li> </ul>	

Reviewer's Init	ials: Date:	
□Yes □No	Request for unrestricted release Group 2 or >. Consult with Bravo Branch.	
□Yes □No	Termination request < 90 days from date of expiration	
□Yes □No	Expedite (medical emergency, no RSO, location of use/storage not on license, RAM in possession not on license, other)	
□Yes □No	TAR needed to complete action.	
Branch Chief's and/or HP's Initials: Date:		

SUNSI Screening according to RIS 2005-31			
□Yes  VNo Sensitive and Non-Publicly Available if any item below is checked			
General guidance:			
RAM = or > than Category 3 (Table 1, RIS 2005-31), use Unity Rule Exact location of RAM (whether = or > than Category 3 or not) Design of structure and/or equipment (site specific) Information on nearby facilities Detailed design drawings and/or performance information Emergency planning and/or fire protection systems			
Specific guidance for medical, industrial and academic (above Category 3): RAM quantities and inventory Manufacturer's name and model number of sealed sources & devices Site drawings with exact location of RAM, description of facility RAM security program information (locks, alarms, etc.) RAM security program information (locks, alarms, etc.) 			

DATE

This is to acknowledge the receipt of your letter/application dated 5-09-08, and to inform you that the initial processing,

which includes an administrative review, has been performed.

Ø	

There were no administrative omissions. Your application will be assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card:

The action you requested is normally processed within 90 days.

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number**  $\frac{471839}{71839}$ When calling to inquire about this action, please refer to this mail control number. You may call me at 817-860-8103.

Sincerely,

Colleen Murnehan

NRC FORM 532 (RIV) (10-2006)

Licensing Assistant

BETWEEN:	: (FOR LFMS USE) : INFORMATION FROM LTS
License Fee Management Branch, ARM and	: Program Code: 03120 : Status Code: 0
Regional Licensing Sections	: Fee Category: 3P : Exp. Date: 20150228 : Fee Comments:
	: Decom Fin Assur Reqd: N

..........

LICENSE FEE TRANSMITTAL

A. REGION

- APPLICATION ATTACHED Applicant/Licensee: BASIN ELECTRIC POWER COOPERATIVE Received Date: 20080613 Docket No: 3014682 Control No.: 471839 License No.: 33-18224-01 Action Type: Amendment
- 2. FEE ATTACHED Amount: Check No.:
- 3. COMMENTS

1 Gen Signed Date 10 -

- B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone O3 is entered /\_\_/)
- 1. Fee Category and Amount:
- 2. Correct Fee Paid. Application may be processed for: Amendment Renewal License
- 3. OTHER




Equal Employment Opportunity Employer M/F/D/V ADDRESS SERVICE REQUESTED



JUN 1 3 2008

## DNMS

.\*



Sectors T SUC 361 Substance Substance US PCC MAR

JAMES L. MONTGOMERY NUCLEAR MATERIALS SAFETY BRANCH B UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TX 76011-4005



.

۴

Your Touchstone Energy\* Cooperative 🔊

EGUMLM1 76011

Annala Barbaran Anarthela Bharbara I. Marbara Bara