

PMBelCOL PEmails

From: Tanya Simms
Sent: Friday, July 11, 2008 1:00 PM
To: 'rgrumbir@gmail.com'; 'alsterdis@tva.gov'; 'erg-xl@cox.net'; 'pshastings@duke-energy.com'; 'Ray, Phillip M'; 'kslays@duke-energy.com'; 'Bob Hirmanpour'
Cc: Joseph Sebrosky; PMBelCOL PEmails
Subject: Draft RAI 290 Related SRP Section 9.1.4 for Bellefonte Units 3 and 4
Attachments: RAI 290 draft.pdf

To All,

Attached is Draft RAI 290 related to SRP Section 9.1.4 for Bellefonte Units 3 and 4. Please contact me if you desire a phone conference regarding this RAI. If no response is heard by close of business July 15, 2008, the final RAI will be issued.

Tanya Simms
Project Manager
New Reactor Licensing
U.S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, Maryland 20852-2738
301-415-1387
tanya.simms@nrc.gov

Hearing Identifier: Bellefonte_COL_Public_EX
Email Number: 416

Mail Envelope Properties (C4A4C9A16294FB4CBA5A36312D05FFAC0A9C71ECF7)

Subject: Draft RAI 290 Related SRP Section 9.1.4 for Bellefonte Units 3 and 4
Sent Date: 7/11/2008 1:00:18 PM
Received Date: 7/11/2008 1:00:18 PM
From: Tanya Simms

Created By: Tanya.Simms@nrc.gov

Recipients:

"Joseph Sebrosky" <Joseph.Sebrosky@nrc.gov>
Tracking Status: None
"PMBelCOL PEmails" <PMBelCOL.PEmails@nrc.gov>
Tracking Status: None
"rgrumbir@gmail.com" <rgrumbir@gmail.com>
Tracking Status: None
"alsterdis@tva.gov" <alsterdis@tva.gov>
Tracking Status: None
"erg-xl@cox.net" <erg-xl@cox.net>
Tracking Status: None
"pshastings@duke-energy.com" <pshastings@duke-energy.com>
Tracking Status: None
"Ray, Phillip M" <pmray@tva.gov>
Tracking Status: None
"kslays@duke-energy.com" <kslays@duke-energy.com>
Tracking Status: None
"Bob Hirmanpour" <bobhirman@live.com>
Tracking Status: None

Post Office: HQCLSTR02.nrc.gov

Files	Size	Date & Time
MESSAGE	524	7/11/2008 1:00:18 PM
RAI 290 draft.pdf	14273	

Options

Priority: Standard
Return Notification: No
Reply Requested: Yes
Sensitivity: Normal
Expiration Date:
Recipients Received:

Request for Additional Information No. 290 Revision 0
Bellefonte Units 3 and 4
TVA
Docket No. 52-014 and 52-015
SRP Section: 09.01.04 - Light Load Handling System (Related to Refueling)
Application Section: 9.1.4

QUESTION Balance of Plant Branch 2 (ESBWR/ABWR) (SBPB)

09.01.04-***

RAI-9.1.4-SBPB-01 AP1000 DCD Revision 16 Section 9.1.6.5, "Inservice Inspection Light Load Handling System," states that the COL applicant is responsible for a program for inservice inspection of the light load handling system as specified in Section 9.1.4.4 of the DCD Revision 16. This is identified as COL Information Item 9.1-5. In Section 9.1.4.4 of the Bellefonte COLA, the applicant has responded to this COL information item by stating "STD COL 9.1-5 The above requirements are part of the plant inspection program for the light load handling system, which is implemented through procedures. In addition to the above inspections, the procedures reflect the manufacturer's recommendations for inspection." Please verify that these procedures are established as stated in the COL information item (in the DCD Revision16) and STD COL 9.1-5 (in the COLA) and are currently available for NRC inspection or provide the schedule in relation to fuel loading for issuance of the procedures and describe how this action will be tracked to ensure completion of the COL information item.