400 Chestnut Street Tower II

May 26, 1981

" Copp

WBRD-50-390/81-44 WBRD-50-391/81-43

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - CVCS ANALYTICAL PIPING MODEL ERRORS - WBRD-50-390/81-44 AND WBRD-50-391/8.-43 - SECOND INTERIM REPORT

The subject deficiency was initially reported to MRC-OIE Inspector R. V. Crlenjak on April 28, 1981, in accordance with 10 CFR 50.55(e) as MCR WBM CEB 8107. Our first interim report was submitted on May 28, 1981. TVA has reanalyzed the piping problems with the correct data and is currently reviewing support drawings. We expect to submit our next report by September 16, 1981.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager

Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
51/0