

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

1-1028 AB: 22
August 18, 1981

WBRD-50-390/81-40
WBRJ-50-391/81-39

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - VALVE MODELING ERROR -
WBRD-50-390/81-40 AND WBRD-50-391/81-39 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on April 10, 1981 in accordance with 10 CFR 50.55(e) as NCR WBN CEB 8106. Our first interim report was submitted on May 11, 1981. We expect to provide additional information by September 23, 1981. TVA is continuing to reanalyze the piping problem with the correct valve modeling. We will provide further information in our next report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

A handwritten signature in cursive script that reads "L. M. Mills".

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IF27
S/D

8108240193 810818
PDR ADOCK 05000390
S PDR