

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

83 OCT 18 1983
October 18, 1983: 08

WBRD-50-390/83-39
WBRD-50-391/83-39

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - SENSING OF PIPE BREAKS IN COMPONENT
COOLING SYSTEM - WBRD-50-390/83-39, WBRD-50-391/83-39 - SUPPLEMENTAL
INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector
Linda Watson on June 24, 1983 in accordance with 10 CFR 50.55(e) as
NCR WBN MEB 8301. Our first interim report and final report were submitted
on July 22 and September 9, 1983, respectively.

A typographical error was identified in our final report on this
matter. The error, under "Corrective Action," identifies that
engineering change notice (ECN) 4235 was issued as corrective action.
The actual ECN number is and should be 4253. Please amend your
records accordingly.

If you have any questions, please get in touch with R. H. Shell at
FTS 853-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

D S Kammer

for L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8310210042 831013
PDR ADOCK 05007390
S PDR

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer

OFFICIAL COPY

LE 27

1/0