

**TENNESSEE VALLEY AUTHORITY**

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

August 27, 1981

WBRD-50-390/81-39  
WBRD-50-391/81-38

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

**WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENCIES IN BOX ANCHORS AND  
HANGER LUGS - WBRD-50-390/81-39, WBRD-50-391/81-38 - THIRD INTERIM  
REPORT**

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on April 10, 1981, in accordance with 10 CFR 50.55(e) as NCR 2795R1. Interim reports were submitted on May 11 and June 18, 1981. TVA is continuing the investigations to determine appropriate corrective actions for this deficiency. We expect to provide additional information by November 6, 1981.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

FE27  
S  
1/0