

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

September 30, 1981

WBRD-50-390/81-60
WBRD-50-391/81-56

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - VENDOR WELDS IN TRITIATED AND FLOOR DRAIN COLLECTOR TANKS - WBRD-50-390/81-60, WBRD-50-391/81-56
- SECOND INTERIM REPORT


The subject deficiency was initially reported to NRC-OIE Inspector P. Taylor on July 7, 1981, in accordance with 10 CFR 50.55(e) as NCR 3380R. Our first interim report was submitted on August 7, 1981. We expect to submit our next report by November 17, 1981. We consider 10 CFR Part 21 applicable to this deficiency.

TVA and Westinghouse are continuing to investigate the subject deficiencies to determine what corrective actions are necessary.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

for 
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE-9
S/0