

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

February 2, 1983

05000390

U.S. Nuclear Regulatory Commission  
Region II

Attn: Mr. James P. O'Reilly  
Regional Administrator  
101 Marietta Street - Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - IMPROPER WELD ATTACHMENT OF SHEAR  
LUGS - NCR 2451R - SUPPLEMENT TO FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on October 30, 1980 in accordance with 10 CFR 50.55(e). Our first interim report was submitted on December 1, 1980. TVA submitted a final report on NCRs 2451R and 2882R on January 26, 1981. As discussed with Inspector R. V. Crlenjak on October 6, 1981, TVA has determined that further interim reports are necessary to resolve this deficiency. NCRs 3632R and 3674R have been added to the original NCRs due to their similar nature. Further interim reports were submitted on November 4, 1981 and January 25, March 22, August 10, and October 25, 1982. Our final report was submitted on December 13, 1982.

In our final report, TVA committed to complete all corrective actions associated with the subject NCR by January 31, 1983. However, as discussed with NRC-OIE Inspector P. Fredrickson on January 31, 1983, the date of January 31, 1983 for completion of the corrective actions was not met. There are less than 10 supports requiring additional corrective action.

The corrective actions on this matter will be completed by February 15, 1983.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*DS Kammer*

*for* L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8302140055 830202  
PDR ADOCK 05000390  
S PDR

OFFICIAL COPY

IE 27

13 FEB 4 1983 25