# TENNESSEE VALLEY AUTHORITY

CHATTANOOGA. TENNESSEE 37401

400 Chestnut Street Tower II

November 417, 1980

SERVICES UNIT

U. S. Nuclear Regulatory Commission Director of Reactor Construction Inspection, Office of Inspection and Enforcement Washington, DC 20555

Dear Sir:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-09 - RII: JPO 50-327, -328, -390, -391, -438, -439, -566, -567 - SEQUOYAH, WATTS BAR, BELLEFONTE, AND YELLOW CREEK NUCLEAR PLANTS

The subject letter dated April 17, 1980, transmitted IE Bulletin 80-09 on Eydramotor Actuator Deficiencies. My letter to you dated June 16, 1980, transmitted TVA's initial response to the bulletin, and my letter to you dated October 16, 1980, transmitted an updated response. Enclosed is further information on TVA's continuing research into this concern. We expect to submit further information by February 26, 1981.

If you have any questions, please get in touch with D. L. Lembert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

Enclosure

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

#### ENCLOSURE

SEQUOYAH, WATTS BAR, BELLEFONTE, AND YELLOW CREEK NUCLEAR PLANTS UPDATED RESPONSE TO IE BULLETIN 80-09 HYDRAMOTOR ACTUATOR DEFICIENCIES

TVA initiated a study to locate any ITT General Controls Models AH-90 and NH-90 Series Hydramotor Actuators which may have been supplied to Sequoyah, Watts Bar, Bellefonte, or Yellow Creek. This study included review of TVA documentation and inquiries of the companies in the attached list.

The only suppliers identified to date of the AH-90 or NH-90 Series Hydramotor Actuators to any of the subject nuclear plants are ACDC, American Warming and Ventilation, Posi Seal International, and Ruskin. The subject actuators have been supplied to Watts Bar and Bellefonte.

TVA's investigation has also uncovered use of the subject actuators as part of valve actuators. At this time, TVA plans to get in touch with major valve suppliers to determine if any more of the subject actuators were supplied to TVA as part of valve actuators.

TVA has been documenting the disposition of the subject actuators as nonconformance reports and will continue to do so if more of the autuators are identified.

### ATTACHMENT

## HYDRAMOTOR ACTUATORS COMPANIES CONTACTED BY TVA

Company	Type of Response	Notes
ACDC, Inc.		
American Warming & Vent Co., Inc.		(2)
Copes-Vulcan, Inc.		(2)
Fisher Controls Co., Inc.	Written	(1)
General Signal Co., Inc.	Written	(1)
General Signal Corporation TT Hammel-Dahl	See BIF	(1)
	-/	(2)
Joy Manufacturing	Written	(1)
Masoneilan International, Inc.	Written	(1)
Pacific Air Products	Written	(1)
Posi Seal International, Inc.		(2)
Powers Regulator	Written	(1)
Ruskin Manufacturing Company	Written	(2)
laltek, Incorporated	Written	(1)
Flakt Products	Written	(1)
CTI Nuclear	Verbal	
BIF	Written	(1)
C. F. Braun	Written	(1)
GE	하면 되는 그렇게 하다면 전 경험을 되게 하루기 되었다. 그리고 하다 하다 하다 그리고	(1)
B&W	Written	(1) -
CE	Written	(1)
Westinghouse	Written	(1)
accorn@iouse	Written	(1)

### NOTES:

- (1) None supplied to date to Sequoyah, Watts Bar, Bellefonte, or Yellow Creek
- (2) Supplied the subject actuators to Bellefonte and/or Watts Bar