

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

May 19, 1981



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - SEISMIC ANALYSIS OF CHECK VALVE
IN CVCS - WBN CEB 8007 - FIFTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. Thomas on October 2, 1980, in accordance with 10 CFR 50.55(e).
Interim reports were submitted on October 31, 1980, January 6, 1981, and
February 10 and March 17, 1981.

TVA has not received the results of the reanalysis from Gilbert
Commonwealth concerning the failure to consider the weight of a 3-inch
check valve in the seismic analysis of the CVCS at Watts Bar. Further
information will be supplied in our final report by July 23, 1981.

If you have any questions, please get in touch with D. L. Lambert at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/0

8105260376

S