

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

July 15, 1982

WBRD-50-390/81-23

WBRD-50-391/81-47

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - POWER OPERATED RELIEF VALVES DO NOT MEET REQUIREMENTS - WBRD-50-391/81-47 - ADDITIONAL SUPPLEMENTAL INFORMATION


The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on May 6, 1981 in accordance with 10 CFR 50.55(e) as NCR WDN 3128R. Interim reports were submitted on June 5 and August 14, 1981. Our final report was submitted on October 6, 1981, and supplemental information was provided on January 25, 1982.

As discussed with NRC-OIE Inspector J. D. Wilcox on June 30, 1982, the date of March 1, 1982 for completion of corrective actions indicated in our last report on this matter was not met. On unit 1, one hanger requires redesign and will be installed by July 1, 1983. The rework required for unit 2 will be completed July 1, 1984.

If you have any questions, please get in touch with R. H. Shell at
PTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

IE 27