TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 5N 157B Lookout Place

January 31 & 19862 : [] 6

WBRD-50-391/84-25

U.S. Nuclear Regulatory Commission Region II Attention: Dr. J. Nelson Grace, Regional Administrator 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - FAILURE TO PROVIDE FIRE DETECTORS IN ROOMS CONTAINING REDUNDANT SAFE SHUTDOWN CIRCUITS - WBRD-50-391/84-25 - SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on May 11, 1984 in accordance with 10 CFR 50.55(e) as NCR WBN MEB 8415. Below is a supplemental final report for unit 2.

The date of December 31, 1984 for completion of corrective actions indicated in our final report on this matter was not met. A review of unit 2 commitments has identified that the commitment to install unit 2 fire detectors has not been completed but that work is continuing under ECN 4872.

The corrective action on this matter will be completed by February 1, 1986.

If there are any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. L. Gridley
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

B602200632 B60131 PDR ADOCK 05000391 PDR