

DBI, Inc. Quality Inspection and Consulting Services

Reliable...Responsive...Resourceful...Proactive

June 24, 2008

RECEIVED

JUL 01 2008

DNMS

U.S. Nuclear Regulatory Commission
Region IV
612 E. Lamar Blvd., Suite 400
Arlington, TX 76011-4125

Attention: Rachel Browder
Health Physicist

Dear Ms. Browder,

The following is in response to the deficiencies on the facsimile dated June 24th, 2008 for pending NRC License No. 49-29301-01:

Deficiency #1. Clarification for Calibration of Instruments.

- a. DBI, Inc. will perform their own calibration of instruments as per the Operating and Emergency Procedure, QCP #4125vr1, under the NRC License listed above. A cesium source will be purchased for this purpose as soon as the NRC License is official.

Deficiency #2. Training radiographers and assistant radiographers on 10 CFR Sections 30.7, 30.9, and 30.10.

- a. DBI, Inc. will in addition to QCP #4125vr1, Section 8, provide training to the radiographers and assistant radiographers for 10 CFR 30.7, for employee protection, 10 CFR 30.9, completeness and accuracy of information and 10 CFR 30.10, deliberate misconduct.

Deficiency #3 Monitoring of a package as required by 10 CFR 20.1906 as soon as practical.

- a. DBI, Inc. will abide by 10 CFR 20, 1906 for monitoring of a package as soon as practical after receipt of the package. The word "immediate" was removed from the statement on page 25 of our Procedure, QCP #4125vr1, Section 3, Number 5 (a) Receipt Radioactive Material.


Lincoln, Nebraska
5330 N. 57th Street
Lincoln, NE 68507
Telephone: (402) 467-1818
Fax: (402) 467-1766

Omaha, Nebraska
2211 S. 156th Circle
Omaha, NE 68130
Telephone: (402) 330-9612
Fax: (402) 330-9640

Overland Park, Kansas
11660 West 90th
Overland Park, KS 66214
Telephone: (913) 888-2321
Fax: (913) 888-2351

Carter Lake, Iowa
520 Locust
Carter Lake, IA 51510
Telephone: (712) 347-5296
Fax: (712) 347-5297

Casper, Wyoming
1909 Salt Creek Hwy.
Casper, WY 82601
Telephone: (307) 235-9027
Fax: (307) 235-9082



DBI, Inc. Quality Inspection and Consulting Services

Reliable...Responsive...Resourceful...Proactive

- Deficiency #4 Proper Shipping Name on transportation paperwork.
- a. DBI, Inc. will abide by 49 DFR 172. 101. The Shipping Paper has been corrected with the proper shipping name for Iridium-192.
- Deficiency #5 Providing annual reports of exposures for individuals working in an NRC Jurisdiction as required by 10 CFR 20.2206.
- a. DBI, Inc. will provide exposure reports annually to the NRC for individuals working in an NRC jurisdiction by April 30th for the previous year.
- Deficiency #6 New address for the NRC Region IV Office.
- a. The new NRC address has been updated in DBI, Inc.'s Procedure QCP 4125vr1, Section 7, Notification of Incidents, page 36.

If you need any further information please feel free to contact me at (402) 467-1818.

Sincerely,

Pennie Frye
Corporate Radiation Safety Officer

Lincoln, Nebraska
5330 N. 57th Street
Lincoln, NE 68507
Telephone: (402) 467-1818
Fax: (402) 467-1766

Omaha, Nebraska
2211 S. 156th Circle
Omaha, NE 68130
Telephone: (402) 330-9612
Fax: (402) 330-9640

Overland Park, Kansas
11660 West 90th
Overland Park, KS 66214
Telephone: (913) 888-2321
Fax: (913) 888-2351

Carter Lake, Iowa
520 Locust
Carter Lake, IA 51510
Telephone: (712) 347-5296
Fax: (712) 347-5297

Casper, Wyoming
1909 Salt Creek Hwy.
Casper, WY 82601
Telephone: (307) 235-9027
Fax: (307) 235-9082