

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

November 8, 1983

USNRC REGION II
ATLANTA, GEORGIA
NOV 15 9:48

WBRD-50-390/82-70
WBRD-50-391/82-67

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - STEAM GENERATOR LOWER SUPPORT BOLTS
- WBRD-50-390/82-70, WBRD-50-391/82-67 - SUPPLEMENTAL INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on June 10, 1982 in accordance with 10 CFR 50.55(e) as NCR GEN NEB 8201. Interim reports were submitted on July 9, and October 28, 1982 and April 15, 1983. Our final report was submitted on September 30, 1983. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector Paul Fredrickson on October 24, 1983, the date of October 27, 1983 for completion of corrective actions indicated in our final report on this matter would not be met. Due to difficulties in the removal and shipping of some of the unit 2 steam generator lower support bolts, the completion date was rescheduled. All bolts have now been shipped to Singleton Labs for completion of reheat treatment. The corrective action on this matter will be completed by November 27, 1983.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

8311210175 831108
PDR ADOCK 05000390
S PDR

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

IE 27

1/b