

TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

APR 22 9:28

April 14, 1986

WBRD-50-391/83-16

U.S. Nuclear Regulatory Commission
Region II

Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - LOOSE MATERIAL IN STEAM GENERATOR -
WBRD-50-391/83-16 - SUPPLEMENTAL FINAL REPORT


The subject deficiency was initially reported to NRC-OIE Inspector Linda Watson on March 25, 1983 in accordance with 10 CFR 50.55(e) as NCR 4715. Our final report for unit 2 was submitted on October 10, 1984. This constitutes our supplemental final report.

As discussed with Bob Carroll on March 6, the date of March 1, 1986 for completion of the corrective actions indicated in our final report was not met. Flushing of the steam generators cannot be completed until after the secondary side hydrostatic testing which has been rescheduled. This corrective action will be complete before hot functional testing of unit 2.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



R. L. Gridley
Manager of Licensing

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8605060267 860414
PDR ADOCK 05000391
S PDR