

TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

APR 22 1986  
April 14, 1986

WBRD-50-391/83-56

U.S. Nuclear Regulatory Commission  
Region II  
Attention: Dr. J. Nelson Grace, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - LEAKING STEAM GENERATOR HYDRAULIC SNUBBERS -  
WBRD-50-391/85-56 - SECOND SUPPLEMENTAL FINAL REPORT


The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on September 27, 1983 in accordance with 10 CFR 50.55(e) as NCR 5003. Previous reports were submitted on October 24, December 20, 1983, and October 24, 1985. We consider 10 CFR Part 21 applicable to this deficiency. This constitutes our second supplemental final report.

The date of March 30, 1986 for completion of corrective action on this item was not met, as discussed with Inspector Bob Carroll on April 1, 1986. Inspection and test reports for the unit 2 steam generator hydraulic snubbers still have not been received from Paul-Munroe Hydraulics. Installation cannot begin until these reports are received. The corrective action on this matter will be completed before unit 2 hot functional testing.

If there are any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
R. L. Gridley  
Manager of Licensing

cc: Mr. James Taylor, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8605070437 860414  
PDR ADOCK 05000391  
S PDR

1/0

IE 27